




TECHNICAL SERVICE BULLETIN

REF.: DRIVELINE/
DIFFERENTIAL
NO.: DL93-001
DATE: NOVEMBER 12, 1993
MODEL: ST, AT

REAR AXLE BEARING

Page 1 of 2

For parts standardization, the rear axle bearing has been changed as shown below.



Because the outer race has been incorporated into the hub, wheel bearings are no longer available as separate replacement parts. The entire hub/bearing assembly must be replaced.

Previous P/N	Part Name	New P/N	New Part Name	Application
90369-30044	Bearing	42410-20170*	Hub & Bearing Assembly	Without ABS
N/A	Hub & Bearing Assembly	42450-20030**	Hub & Bearing Assembly	With ABS

* This bearing is now only available with the complete Rear Axle Hub Assembly

** For vehicles with ABS, the Rear Axle Hub and Bearing Assembly part number remains unchanged.

TOYOTA MOTOR SALES U.S.A., INC.

REAR AXLE BEARING

Page 2 of 2

REPAIR PROCEDURE:

The new style Rear Axle Hub and Bearing Assembly can be used on all ST and AT Celicas. The previous part number Rear Axle Bearing can be used only on vehicles built before the production change.

PRODUCTION EFFECTIVE:

VIN	Date
JT2AT86F#P0112788	July 1993
JT2ST8###P0149738	July 1993