



Technical Service BULLETIN

March 6, 1998

Title:

FRONT AXLE HUB NUT REPLACEMENT

Models:

'92 – '98 Tercel, Paseo, Corolla, Celica, Camry
'96 – '98 RAV4


DL001-98

DRIVELINE/DIFFERENTIAL

Introduction Due to a change of the friction control treatment on the nut thread, both types of Front Axle Hub Nuts (silver and black) for 1992 – 1998 Tercel, Paseo, Corolla, Celica, Camry and 1996 – 1998 RAV4s are **NOT reusable**.

NOTE:

When replacing the Front Axle Hub Nut the new part must be the same color as the old part. When replacing a Silver nut -- use a NEW Silver nut and when replacing a Black nut -- use a NEW Black nut.



Affected Vehicles

- 1992 – 1998 Tercel, Paseo, Corolla, Celica, Camry and 1996 – 1998 RAV4s.

Parts Information

PART NUMBER	PART NAME	COLOR
90179-22020	Nut, Axle Hub	Silver
90178-22001	Nut, Axle Hub	Black

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—

