




REF.: PRODUCT GENERAL
INFORMATION
NO.: PG93-001
DATE: JANUARY 1, 1993
MODEL: ALL MODELS

1993 TECHNICAL SERVICE BULLETIN GENERAL INFORMATION

Page 1 of 1

Toyota Service Bulletins (TSBs) continue to be the most current information available on Toyota products, and Toyota has taken the following steps to help ensure complete access to this reference source:

- During the month of March, service personnel will receive a bound book containing all TSBs issued in 1992. Upon receipt of this book, all 1992 bulletins in your TSB binder may be discarded or relocated to an empty binder. The TSB binder should then be used for new 1993 bulletins beginning with this shipment.
- When the need arises, additional TSB material can be ordered through the Toyota Non-Parts System by using the following parts numbers:

MATERIAL DESCRIPTION	PART NUMBER
1993 TSB Binder Complete with all Bulletins Issued to Date:	TSB93
TSB Binder and Tabs Only:	00406-61012
1992 TSB Bound Book:	00401-42991★
1991 TSB Bound Book:	00401-42973
1990 TSB Bound Book:	00401-42936
1989 TSB Bound Book:	00401-42900
1988 TSB Bound Book:	00401-42870
1987 TSB Bound Book:	00401-42844
1992 TSB Microfiche:	00406-61015★
1991 TSB Microfiche:	00406-61014
1990 TSB Microfiche:	00406-61013

★ Available in March, 1993

If you have any questions concerning Toyota Service Bulletins, please contact your District Service Manager.