

TOYOTA TECHNICAL SERVICE BULLETIN

REF.: SPECIAL
SERVICE TOOLS
NO.: SS94-002
DATE: AUGUST 12, 1994
MODEL: ALL MODELS

WIRE HARNESS REPAIR KIT "B"

Page 1 of 2



The new Wire Harness Repair Kit "B" has been released as an essential Special Service Tool (SST) to supplement the original Wire Harness Repair Kit. This kit holds an initial supply of 21 new type electrical terminals and connectors as well as the necessary supplies and small tools for most electrical repairs.

The Wire Harness Repair Kit manual has been updated and now contains an illustrated catalog of all terminals and connectors available for Toyota vehicles. Connector Replacement Guidelines, a Connector/Terminal Usage Guide, and a Connector Quick Reference Chart have been added as additional reference. This manual is the only reference available which provides information on properly identifying connectors and terminals.

When components/supplies need to be replaced, refer to page 21 in the manual or the reverse side of this TSB. Note: The manual is no longer available through the Toyota Non-Parts System. It is available separately under part number 410094 by calling OTC at 1-800-933-8335.

WIRE HARNESS REPAIR KIT “B”**PARTS REPLACEMENT ORDERING INFORMATION:**

The following parts can be ordered through Toyota Motor Sales on a normal parts order:

Part Number	Description	Part Number	Description
82998-12010	Repair Splice	82998-12470	Repair Splice
82998-12030	Repair Splice	82998-12490	Repair Splice
82998-12050	Repair Splice	82998-12020	Repair Splice
82998-12070	Repair Splice	82998-12040	Repair Splice
82998-12090	Repair Splice	82998-12060	Repair Splice
82998-12110	Repair Splice	82998-12080	Repair Splice
82998-12130	Repair Splice	82998-12100	Repair Splice
82998-12150	Repair Splice	82998-12120	Repair Splice
82998-12170	Repair Splice	82998-12140	Repair Splice
82998-12190	Repair Splice	82998-12160	Repair Splice
82998-12210	Repair Splice	82998-12180	Repair Splice
82998-12230	Repair Splice	82998-12200	Repair Splice
82998-12250	Repair Splice	82998-12220	Repair Splice
82998-12270	Repair Splice	82998-12240	Repair Splice
82998-12290	Repair Splice	82998-12260	Repair Splice
82998-12310	Repair Splice	82998-12280	Repair Splice
82998-12330	Repair Splice	82998-12300	Repair Splice
82998-12350	Repair Splice	82998-12320	Repair Splice
82998-12370	Repair Splice	82998-12340	Repair Splice
82998-12390	Repair Splice	82998-12360	Repair Splice
82998-12410	Repair Splice	82998-12380	Repair Splice
82998-12430	Repair Splice	82998-12400	Repair Splice
82998-12450	Repair Splice	82998-12420	Repair Splice
216824	Silicon Tape	82998-12440	Repair Splice
00204-34130	18/22 Splice	82998-12460	Repair Splice
00204-34137	14/16 Splice	82998-12480	Repair Splice
00204-34138	10/12 Splice	82998-12500	Repair Splice

The following parts can be ordered from OTC Tool & Equipment Division, SPX Corporation, 655 Eisenhower Drive, Owatonna, Minnesota 55060:

Part Number	Description	Part Number	Description
62164	Tool Box Kit A (Toyota)	310032	Wire Stripper
310044	Tool Box Kit B (Toyota)	310033	Terminal Pick
62166	Tool Box (Lexus)	216820	Terminal Gauge
310031	Crimper (Kit A)	216822	Terminal Gauge
AMP47100-1	Crimper (Kit B)	00002-217681	Terminal Pick
		00002-217958	Terminal Pick
		410094	Repair Manual

All remaining parts can be purchased from a local supplier.

