



Technical Service BULLETIN

February 16, 2001

Title:

STEERING WHEEL NUT SERVICE SPECIFICATION

Models:

All Applicable Models

STEERING
ST001-01

Introduction To make the steering wheel installation procedure similar for all models, the steering wheel nut tightening torque has been standardized.

Applicable Vehicles

MODEL		MODEL YEARS
TERCEL	EL42, 53	1991 – 1998
ECHO	NCP12	2000
PASEO	EL44, 54	1992 – 1997
COROLLA	AE10#, ZZE110	1993 – 2001
CELICA	AT180, ST18#, AT2#, ST2#, ZTZ23#	1990 – 2000
MR2	SW2#, ZZW30	1991 – 1995; 2000
CAMRY	SXV10, 20, MCV10, 20	1992 – 2000
CAMRY CNG	SXV23	2000 – 2001
CAMRY SOLARA	SXV20, MCV20	1999 – 2000
AVALON	MCX10, 20	1995 – 2000
SUPRA	JZA80	1993 1/2 – 1998
RAV4	SXA1#	1996 – 2000
RAV4 EV	BEA11	1998 – 2000
PREVIA	TRC10, 20	1991 – 1997
SIENNA	MCL10	1998 – 2000
HIGHLANDER	ACU20, 25, MCU20, 25	2001
4RUNNER	RN12#, 13#, VZN12#, 13#, 18#, RZN180, 185	1990 – 2000
LAND CRUISER	FZ80, FZJ80, UZJ100	1991 – 2000
TRUCK	RN8#, 9#, 10#, 110, VZN85, 9#, 10#, 110	1989 – 1995
TACOMA	RZN140, 150, 161, 171, 19#, VZN150, 160, 170, 195	1995 1/2 – 2000
T100	VCK10, 20	1993 – 1998
TUNDRA	VCK30, 40, UCK30, 40	2000

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–



Toyota Supports ASE Certification

Service Information

