



TECHNICAL SERVICE BULLETIN

TOYOTA CANADA INC. TECHNICAL OPERATIONS DEPT.

Model	Year Range	Component	Engine	Transmission
All	1986 ~	MI		
Reference	Bulletin	Issue Date		
MI-90-006	0139	1990-06-01		

Subject: CARBON CLEANER / BORESCOPE

The Carbon Cleaner and Ridged Borescope utilized for evaluating and removing possible carbon accumulation on the intake valves has been introduced by letter to each Dealer Principal .

Dealer Technicians have recently received hands-on training on both these items during the Zone Training Sessions .

The purpose of this Bulletin is to update and advise you of the necessary information required if:

* Ordering additional

- Carbon Cleaners
- Ridged Borescopes

* Ordering the required maintenance item


- Filter Bags
- Walnut Shell Media

* Warranty applications and procedures

BORESCOPE

Part No. C0999-09055

The ridged borescope is a high tech way to visually inspect internal engine components for carbon build up , wear , cracks , leaks and contamination . the ridged borescope is not limited to engine inspection only, but may be used if remote inspection is required . It is easy to use. The light source doubles as a high intensity flash light and is powered by a battery pack , coupled to the ridged borescope .



The light source should only be equipped with 2C cells Alkaline Batteries . A replacement light bulb-manufactured by Phillips , model 222 can be purchased at any electronic store.

Warranty Conditions:

The ridged borescope and its light source (excluding the batteries and light bulb) are covered for a period of twelve (12) months against a defect in material and workmanship. This does not apply if the equipment has been misused , abused and/or improperly handled . If the equipment is found to be defective, the complete unit must be packaged in the original carrying case and prepaid, shipped to:

Carsen Industrial


Attn: Service Department
Telephone: 416-479-4100

A short defect description with the returning address of the Toyota Dealer must be included in the carrying case .
A newly reconditioned unit will be returned , prepaid to the sender .

CARBON

* Part No. C0999-16806

The Carbon Cleaner is used to remove any accumulation of Carbon on the intake valve . Cylinder head removal is not required , instead , the intake manifold is removed and an adapter plate is installed . Non abrasive walnut shell media is propelled through a discharge nozzle by compressed air to remove the carbon accumulation . The waste is returned to the filter bag via a return hose . The carbon cleaner is easy to use and adapts to any existing air lines .



* Warranty Conditions

The Carbon Cleaner , excluding filters , hoses and rubber grommets , is covered for a period of twelve (12) months against defect in material and workmanship . This does not apply if the equipment has been misused, abused and/or improperly handled .

If the Equipment is found to be defective , the complete unit , including all hoses and the discharge nozzle must be returned , prepaid to:

Kentmoor Industries
c/o Intex
434 Tecumseh Road East
Windsor, Ontario
18X 2R6

Note: This quotation must be noted: **RETURN/REPAIR GOODS**

A short defect description with the returning address of the Toyota Dealer must be included .

The repaired unit will be returned , prepaid , to the dealer .

* Additional Engine Adapter Plates

Additional Engine Adapter Plates , other than for the 3E Engine , are made available during the course of 1990. Once the Part Numbers and prices are available notification will be issued .

* Part Number Information

Part No	Part Name	Dealer Net Price*
C0999-16806	Carbon Cleaner	\$863.00
C0999-09055	Borescope	\$1445.00
C0009-16425	25lbs pail Walnut Shell Media	\$78.40
C0009-16426	Filter Bags, set of 30 @ \$3.50	\$105.00

These items can only be purchased through your facing PDC using the normal parts ordering procedures .

* Prices quoted are subject to change without notice .

NOTE:

