



TECHNICAL SERVICE BULLETIN

TOYOTA CANADA INC. TECHNICAL OPERATIONS DEPT.

Model	Year Range	Component	Engine	Transmission
4Runner, Camry, Celica, Corolla, Land Cruiser, MR2, Paseo, Supra, T100, Tercel, Truck	1986~1994	EM	1MZ-FE; 2JZ-GE; 3E-E; 3S-GTE; 3VZ-E; 3VZ-FE; 4A-FE; 5E-FE; 5S-FE; 7A-FE	
Reference	Bulletin	Issue Date		
EM-94-005	0422	1994-10-01		

Subject:
WATER PUMP MODIFICATION

The water pumps for the following engine series have been changed to enhance the shaft sealing performance:

PRODUCTION EFFECTIVE:

ENGINE SERIES	MODEL	PRODUCTION DATE
3E-E, 5E-FE 4A-FE, 7A-FE 5S-FE, 3S-GTE 3VZ-E, 3VZ-FE 1MZ-FE 2JZ-GTE	TERCEL, PASEO COROLLA, CELICA CAMRY, CELICA, MR2 T100, TRUCK, 4-RUNNER, CAMRY CAMRY SUPRA	NOVEMBER 18, 1993 SEPTEMBER 23, 1993 NOVEMBER 29, 1993 NOVEMBER 17, 1993 MARCH 18, 1994 JANUARY 14, 1994

NOTE: The part numbers remain unchanged. All Toyota Canada parts stock is of the improved type.

SERVICE HINTS:

- In the event of a customer complaint of a coolant leak requiring the replacement of the water pump, it is recommended that a normal coolant flush be performed before replacing the water pump.
- Use Toyota genuine Long Life Coolant (Part No. C0009-00119) or equivalent (non-Amine type).

NOTE:

Issue of this Technical Service Bulletin is to ensure that proper repair information is available. IT DOES NOT CONSTITUTE AN AUTHORIZATION FOR REPAIR. Normal provisions of the formal warranty policy, as applicable, will apply.