# MPEG4/H.263 Decoder Version 01.00.16 Release Notes December 2017

# **Build ID: 01.00.16.01**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

# **New In This Release**

Please refer Fixed In This Release section

| Release<br>Configuration | Description  | Validation Platform                           |
|--------------------------|--|---|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on HDVICP2 and Media Controller Based SOCs | DM81x REV-A2 DDR2 EVM [Datasheet][User Guide] |

- This release is dependent on the following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 5.0.3 for Media Controller Processor and 4.5.1 for HDVICP2 processor
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.23)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description  | Applicable<br>Release<br>Configuration |
|---------------|--|--|
| OMAPS00343913 | Issue with FLUSH during Dynamic Resolution change. | IVAHD_001                              |

# **Known Issues**

• None



# MPEG4/H.263 Decoder Version 01.00.15 Release Notes April 2015

# **Build ID: 01.00.15.01**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

· Please refer Fixed In This Release section

| Release<br>Configuration | Description  | Validation Platform                           |
|--------------------------|--|---|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on HDVICP2 and Media Controller Based SOCs | DM81x REV-A2 DDR2 EVM [Datasheet][User Guide] |

- This release is dependent on the following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 5.0.3 for Media Controller Processor and 4.5.1 for HDVICP2 processor
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.23)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description  | Applicable<br>Release<br>Configuration |
|---------------|--|--|
| SDOCM00115792 | Video Blockiness observed in dual-instance decoding case | IVAHD_001                              |

# **Known Issues**



# MPEG4/H.263 Decoder Version 01.00.14 Release Notes November 2013

# **Build ID: 01.00.14.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

## **New In This Release**

• Please refer Fixed In This Release section

| Release<br>Configuration | Description  | Validation Platform                           |
|--------------------------|--|---|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on HDVICP2 and Media Controller Based SOCs | DM81x REV-A2 DDR2 EVM [Datasheet][User Guide] |

- This release is dependent on the following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.22)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description                                  | Applicable<br>Release<br>Configuration |
|---------------|--|--|
| OMAPS00300818 | Video Decode: Fix Video decoder testing bugs | IVAHD_001                              |

# **Known Issues**

• None



# MPEG4/H.263 Decoder Version 01.00.13 Release Notes August 2013

# **Build ID: 01.00.13.01**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

# **New In This Release**

Please refer Fixed In This Release section

| Release<br>Configuration | Description  | Validation Platform                           |
|--------------------------|--|---|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on HDVICP2 and Media Controller Based SOCs | DM81x REV-A2 DDR2 EVM [Datasheet][User Guide] |

- This release is dependent on the following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.22)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description  | Applicable<br>Release<br>Configuration |
|---------------|--|--|
| SDOCM00103095 | Hang is seen at OMX/system when MPEG4 decoder is fed with stream with multiple skip frames | IVAHD_001                              |

# **Known Issues**



# MPEG4/H.263 Decoder Version 01.00.12 Release Notes June 2013

# **Build ID: 01.00.12.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

Please refer to the fixed in this release section for details.

| Release<br>Configuration | Description                             | Validation Platform   |
|--------------------------|---|-----------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM |
|                          | HDVICP2 and Media Controller Based SOCs | Datasheet User Guide  |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description   | Applicable<br>Release<br>Configuration |
|---------------|---|--|
| OMAPS00294564 | Divide by zero exception in MPEG4 codec control call for get status | IVAHD_001                              |
| OMAPS00294164 | H.263 hardware codec returns wrong error code for ANNEX D streams   | IVAHD_001                              |

# **Known Issues**

• None



# MPEG4/H.263 Decoder Version 01.00.11 Release Notes October 2012

# **Build ID: 01.00.11.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

## **New In This Release**

• Please refer to the fixed in this release section for details.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



Defect ID Description Applicable Release Configuration

Codec returns error if output buffers provided are mix of RAW and TILEDPAGE OMAPS00281195

IVAHD\_001

# **Known Issues**



# MPEG4/H.263 Decoder Version 01.00.10 Release Notes July 2012

# **Build ID: 01.00.10.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

• Added feature to support decoding of only Intra frames with less create time memory. Please refer Datasheet for gain in memory in this feature.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



None

# **Known Issues**

• None



# MPEG4/H.263 Decoder Version 01.00.09 Release Notes June 2012

# **Build ID: 01.00.09.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

## **New In This Release**

• Please refer to the fixed in this release section for details.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Tool version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description   | Applicable Release Configuration |
|---------------|---|----------------------------------|
| SDOCM00093580 | In case of H263++ streams, frames without UFEP are not decoded properly. ECD3 throws out error. | IVAHD_001                        |
| OMAPS00273469 | MPEG4 decoder is not populating frame rate of status params correctly                           | IVAHD_001                        |

# **Known Issues**

• None



# MPEG4/H.263 Decoder Version 01.00.08 Release Notes June 2012

# **Build ID: 01.00.08.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

## **New In This Release**

• Please refer to the fixed in this release section for details.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Toll version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description   | Applicable Release Configuration |
|---------------|---|----------------------------------|
| SDOCM00093154 | Posted write problem from M3. Hang on Media Controller can be observed, if SL2 is accessed through buffered region from Media Controller. | IVAHD_001                        |
| SDOCM00093428 | Uninitialized parameter - "interlaced" in header structure.   | IVAHD_001                        |

# **Known Issues**



# MPEG4/H.263 Decoder Version 01.00.07 Release Notes May 2012

# **Build ID: 01.00.07.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

• Added support for enhanced out loop Deblocking Feature

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD 001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Toll version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



Defect ID Description Applicable Release Configuration

SDOCM00089567 More clarifications in data sheet IVAHD\_001

**Known Issues** 



# MPEG4/H.263 Decoder Version 01.00.06 Release Notes March 2012

# Build ID: 01.00.06.00

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

• Please refer the fixed in this release section for details. Please refer the data sheet for detail feature list.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Toll version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



Defect ID Description Applicable Release Configuration

MPEG4 Corrupted clip - Occurs sorry cannot player OMAPS00262600

pop-up

Codec freeing single buffer instead of two buffers when display delay set to decode order SDOCM00090501

**Known Issues** 

Defect ID Applicable Release Description

Configuration

IVAHD\_001

More clarifications in data sheet. SDOCM00089567 IVAHD\_001



# MPEG4/H.263 Decoder Version 01.00.05 Release Notes February 2012

# **Build ID: 01.00.05.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

 Please refer the fixed in this release section for details. Please refer the data sheet for detail feature list.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Toll version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



Defect ID Description Applicable Release

Configuration

VOL header corrupted clip stops playing and showing pop up message video cant played. OMAPS00262190

IVAHD\_001

**Known Issues** 

Applicable Release Configuration Defect ID Description

More clarifications in data sheet. SDOCM00089567 IVAHD\_001



# MPEG4/H.263 Decoder Version 01.00.04 Release Notes January 2012

# **Build ID: 01.00.04.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

 Please refer the fixed in this release section for details. Please refer the data sheet for detail feature list.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Toll version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



Defect ID Description

Applicable Release Configuration

OMAPS00259817

A block noise is displayed on the lower right of the picture.

IVAHD\_001

**Known Issues** 



# MPEG4/H.263 Decoder Version 01.00.03 Release Notes November 2011

# **Build ID: 01.00.03.01**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

### **New In This Release**

• Please refer the fixed in this release section for details. Please refer the data sheet for detail feature list.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Toll version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



Defect ID
Description
Applicable Release
Configuration

OMAPS00252022
MPEG-4 outArg's display buffer descriptors don't match the
display buffer.

OMAPS00255460
MPEG-4 Dec Codec Lib causing corruption after seek
IVAHD\_001

# **Known Issues**



# MPEG4/H.263 Decoder Version 01.00.03 Release Notes November 2011

# **Build ID: 01.00.03.00**

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issue

## **New In This Release**

• Please refer the fixed in this release section for details. Please refer the data sheet for detail feature list.

| Release<br>Configuration | Description                             | Validation Platform     |
|--------------------------|---|-------------------------|
| IVAHD_001                | MPEG4/H.263 Decoder, which runs on      | DM81x REV-A2 DDR2 EVM   |
|                          | HDVICP2 and Media Controller Based SOCs | [Datasheet][User Guide] |

- This release is validated on DM816x REV-A2 DDR2 EVM using following components
  - Code Composer Studio (CCSv4) version 4.2.0.09000
  - Code Generation Toll version 4.5.1
  - Framework Component version 3.20.00.22
  - HDVICP2 API (01.00.00.19)
  - HDVCIP2 CSP (Containing CSL) version 00.05.00.20
  - BIOS version 6.30.02.42
  - Codec Engine (CE) version 3.20.00.16
  - XDC tool version 3.20.04.68



| Defect ID     | Description  | Applicable Release Configuration |
|---------------|--|----------------------------------|
| OMAPS00250564 | Mpeg4 de-blocking feature does not work: green blocks are shown all along the video clip incase codec gets internal buffers allocated in tiler region. | IVAHD_001                        |
| OMAPS00252437 | Codec report fatal error while playing the H.263 movie clip  | IVAHD_001                        |
| SDOCM00083334 | MPEG4 Decoder is having issue while transferring the static table to SI2   | IVAHD_001                        |
| SDOCM00083458 | In MPEG4 Decoder some of erroneous stream decoded output is having block ness.   | IVAHD_001                        |
| SDOCM00084258 | MPEG4 Decoder on HDVCIP2 is not having support for 2K-2K error concealment even though having support for decoding of 2Kx2K.                           | IVAHD_001                        |
| SDOCM00084955 | MPEG4/H263 decoder returning error as unsupported Parameters while changing the display width through control call.                                    | IVAHD_001                        |
| SDOCM00085157 | Concealment of some of erroneous streams are not happening correctly in case of MPEG4/H.263 decoder  | IVAHD_001                        |
| SDOCM00085158 | Dynamic resolution change is not supported in MPEG4/H.263 decoder  | IVAHD_001                        |
| SDOCM00085159 | Drop of first Frame (I Frame) in sequence is not getting reported by H.263 codec   | IVAHD_001                        |
| SDOCM00085160 | Copying of MB-status Info from SL2 Memory to DDR may create issue  | IVAHD_001                        |
| SDOCM00085269 | MPEG4/H.263 decoder is wrongly decoding the erroneous spark stream   | IVAHD_001                        |
| SDOCM00085268 | MPEG4/H263 decoder should have common test app as other codec's  | IVAHD_001                        |
| SDOCM00083990 | make batch file may not work on windows 7  | IVAHD_001                        |
| SDOCM00082283 | H.263 stream having height more then 800 pixels are not Getting decoded correctly by MPEG4 Decoder, codec reporting error for non-erroneous streams.   | IVAHD_001                        |
| SDOCM00082097 | Hard fault observed with the ice crusher register in HDVCIP_Acquire function, while running H263 erroneous Stream.                                     | IVAHD_001                        |
| SDOCM00082275 | An erroneous H263 stream throws a FATAL error when a valid Start H263 code not found in stream.  | IVAHD_001                        |
| SDOCM00082335 | MPEG4 Decoder returns error for non-corrupted Gob's for Erroneous H.263 streams.   | IVAHD_001                        |
| SDOCM00082539 | MPEG4 decoder is tested with only limited number of positive And negative test cases.  | IVAHD_001                        |
|               |  |                                  |



| Defect ID     | Description  | Applicable Release Configuration |
|---------------|--|----------------------------------|
| SDOCM00082712 | MPEG4 Decoder is corrupting output buffer for erroneous Streams.   | IVAHD_001                        |
| SDOCM00081514 | With outloopDeBlocking = DEBLOCK_ENABLE, for a error stream the display buffer will have filtered output but not concealed for the erroneous frame, but for subsequent frame(s) The concealed output will be used for temporal prediction. | IVAHD_001                        |
| OMAPS00242800 | H263 video clip does not play after few seconds  | IVAHD_001                        |
| OMAPS00242676 | Video playback fails, show "video format is not supported", 1080p and 720p mp4 clip.   | IVAHD_001                        |

# **Known Issues**

