

Compressed Air Sourcebook Sample

PDF fixture for industrial RAG ingestion.

Leak survey records location, estimated leak size, header pressure, and repair owner.

If night shift header pressure falls below 620 kPa, check receiver storage, dryer pressure drop, and compressor cycle.

Heat recovery can route compressor discharge heat to process water or space heating when maintenance risk is controlled.