PS2 键盘接口引脚定义图

PS/2 键盘接口为 6 针母插,外观为:



引脚定义

Pin	Han e	Dir	Description
1	DATA	+	Key Data
2	n/c	-	Not connected
3	GND	_	Gnd
4	VCC	→	Power , +5 VDC
5	CLK	→	Clock
6	n/c	-	Not connected

PS 2 鼠标接口引脚定义图

PS/2 鼠标接口为 6 针母插,外观为:



引脚定义

Pin	Hane	Dir	Description
1	DATA	+	Key Data
2	n/c	4	Not connected
3	GND	_	Gnd
4	VCC	→	Power , +5 VDC
5	CLK	\rightarrow	Clock
6	n/e	-	Not connected