



TWINCO 6900 Pallet Stacking and Loading in 40' Container

10 PCS / Pallet

Loading in 40' Container
40 pallets
40x10=400 PCS



Notes:
1, Use wrapping film and packing belt to pack the whole pallet, the pallet should be stable.
2, warping belt should be tight, but do not damage the product. carton board should be under the belt on the corner.
3, Protection board should be packed on 4 corners as in above picture.

包装要求:
1, 栈板的上表面需先垫一块同等尺寸的纸板;
2, 产品堆叠方式按照图示要求, 产品需放置在栈板的中心位置, 对称整齐分布, 产品在长宽方向不能凸出栈板边缘;
3, 每个托盘上产品的侧面及上表面需用缠绕膜缠好、密封;
4, 四个侧楞需用纸护角保护, 包裹在缠绕膜内部;
5, 需用绑扎带按照图示要求绑紧, 绑扎带拐角与产品接触的位置需用纸板防护。

Date of Change: 15-Jan-2024	Description of Change: Release new drawing.	
Created by:	Approved by: .. .	Doc. Revision: A