Preprocessing and Data Extraction Phase

Peak and Valley Analysis

Identify Settings → Calculate Peaks → Visual Inspection

Bucketing

Pmus Extraction

Pvent Extraction

Flow Extraction

V_T Extraction

Zeroing of data for insp- or expiratory extraction → Simpsons rule integration → Scaling of units