**EDIT** 

remote switchgear system

SORT▼



Breaker 1A tripped in Switchgear 5 - Margaret Hall

June 23, 2014 • 10:36 AM



High vibration levels in Switchgear 6 wiring - Tepper Building

June 12, 2014 • 10:36 AM



Automatically lowered temperature due to Increasing humidity and loose wiring in Switchgear 3 - Simon Building








# switchgear 5 - Margaret Hall Breaker 1A Tripped







**Pictorial** 

One-Line

Floor Map

Why?

A malfunction in chiller 7 caused an overload in Breaker 1A.

Troubleshooting tools






# SWITCHGEAR 5 - MARGARET HALL Breaker 1A Tripped







#### Why?

A malfunction in chiller 7 caused an overload in Breaker 1A.

Troubleshooting tools






### SWITCHGEAR 5 - MARGARET HALL Breaker 1A Tripped







**Pictorial** 

One-Line

Floor Map

Why?

A malfunction in chiller 7 caused an overload in Breaker 1A.

Troubleshooting tools




#### SWITCHGEAR 5 - MARGARET HALL Breaker 1A Trip Event Data



TRIP EVENT DATA

BREAKER SENSORS

SUGGESTED PROTOCOL



Breaker 1A Tripped in Switchgear 5 Margaret Hall

June 23, 2014 • 10:36 AM

Data from Trip Unit Breaker 1A for time of trip event

Voltage 120V (23 over average)

Amps 333A (34 over average)

Phase B Phase

View more detailed information on your power monitoring system



SWITCHGEAR 5 - MARGARET HALL

Breaker 1A Sensors



TRIP EVENT DATA

BREAKER SENSORS

SUGGESTED PROTOCOL

Summary of Breaker 1A's Sensor Data

The breaker has dirt on some components. [UNRELATED TO BREAKER TRIPPING]

Sensors in Breaker 1A	Status	Sensor Condition
Dirt	!	
Fire		
Humidity		
Temperature		
Wiring		

SWITCHGEAR 5 - MARGARET HALL

Breaker 1A Sensors



TRIP EVENT DATA

**BREAKER SENSORS** 

SUGGESTED PROTOCOL

Summary of Breaker 1A's Sensor Data

The breaker has dirt on some components. [UNRELATED TO BREAKER TRIPPING]

Sensors in Breaker 1A	Status	Sensor Condition
Dirt	Dirt on Breaker 1A Two months until problem becomes serious.	
Fire		
Humidity		
Temperature		
Wiring		

## SWITCHGEAR 5 - MARGARET HALL Breaker 1A Trip Fix Instructions



TRIP EVENT DATA

**BREAKER SENSORS** 

SUGGESTED PROTOCOL

Steps for fixing breaker 1A trip.

You will be asked to authenticate to perform these actions remotely.

1. Power automatically rerouted from generator	<b>✓</b>
2. Switch off Switchgear 5.	>
3. Rack out bucket 1 and 3.	>
4. Locate cable 62 and 73.	>
5 Tighten screws on bolts on cable 62 and 73.	>
6. Rack in bucket 1 and 3.	>

# SWITCHGEAR 5 - MARGARET HALL Breaker 1A Trip Fix Instructions



TRIP EVENT DATA

**BREAKER SENSORS** 

SUGGESTED PROTOCOL

Steps for fixing breaker 1A trip.

You will be asked to authenticate to perform these actions remotely.

1. Reroute power from Switchgear 5 to Switchgear 7	<b>✓</b>
2. Switch off Switchgear 5.	<b>✓</b>
3. Rack out bucket 1 and 3.	>
4. Locate cable 62 and 73.	>
5 Tighten screws on bolts on cable 62 and 73.	>
6. Rack in bucket 1 and 3.	