Introduction to Powder Diffraction




Joel Reid, Industrial Scientist, Canadian Light Source

Canadian Powder
Diffraction
Workshop 15

Tuesday, October 11, 2022

Outline


- 1. A brief history of powder diffraction and the Rietveld method.
- An introduction to powder diffraction and Rietveld refinement with applications and examples.
- Examination of the main factors affecting Bragg reflection positions and intensities in Rietveld refinement.




Bragg's Law

 $\lambda = 2d_{hkl}\sin\theta$

Detector









Bragg's Law


$$\lambda = 2d_{hkl}\sin\theta$$




2D powder ring pattern on detector








Ideal powder






Grainy powder



Bragg's Law

 $\lambda = 2d_{hkl}\sin\theta$

Single crystal



Single crystal pattern courtesy of Denis Spasyuk.

- Powder diffraction is a flexible technique for studying crystalline materials with crystal sizes ranging from microns to nanometers, with high information content.
- Powder diffraction can be used to:
 - Identify different crystalline phases in a mixture.
 - Quantify the proportions of different crystalline phases in a mixture, including the amorphous content.
 - Solve and refine the crystal structure of unknown or new crystalline phases.
 - Quantify microstructural features of crystalline materials like strain and the size (shape) of the crystallites.
 - Examine local structure of disordered, poorly crystalline and amorphous materials with Pair Distribution Function (PDF) analysis.



A Brief History of Powder Diffraction

- **1895**: X-rays are first discovered by Wilhelm Röntgen.
- 1912: Max von Laue demonstrates diffraction of X-rays by crystals.
- 1913: The Bragg's demonstrate the solution of crystal structures with diffraction.
- 1916: The first diffraction cameras are independently devised by Debye & Scherrer (Switzerland) and Hull (U.S.).
- 1935: The first powder diffractometer is designed and built by LeGalley.
- **1941**: The Joint Committee for Chemical Analysis by Powder Diffraction Methods (the initial precursor to the ICDD) was founded in 1941 and subsequently created the Powder Diffraction FileTM for phase identification.
- 1947: The first commercial powder diffractometer is introduced by Phillips.



A Brief History of Powder Diffraction (cont.)



Fig. 8. Silicon.




Fig. 10. Magnesium.




Fig. 11. Graphite.



Fig. 12. Diamond.





Fig. 1. Aluminium.



 The powder camera designed by Albert Hull, and some of his initial powder diffraction patterns.

Hull, A. W. Phys. Rev. 10 (1917) 661-696

A Brief History of Powder Diffraction (cont.)




Fig. 1. Diagram of Geiger-Müller counter.




Fig. 3. Diagram of x-ray apparatus.




Fig. 5. Diffraction pattern of KCl.

 The first powder diffractometer, designed by Donald LeGalley, based on a Geiger–Müller tube detector.


LeGalley, D. P. Rev. Sci. Instrum. 36 (1935) 279-283.

A Brief History of Powder Diffraction (cont.)

- 1966-1969: Hugo Rietveld and colleagues develop the whole pattern refinement approach (the Rietveld Method) using neutron powder diffraction data.
- 1977-1978: A number of scientists (including Young, von Dreele, Cox, Malmros, Thomas and Glazer, among others) begin using the Rietveld method with laboratory and synchrotron X-ray powder diffraction data.
- **1986-1988**: The widely used Rietveld programs GSAS (Larson & von Dreele) and FullProf (Rodriguez-Carvajal) are first developed. Rietveld refinement with neutron powder diffraction data proves indispensable in the determination of the structure of the high temperature superconductor, YBa₂Cu₃O_{7-x}, and subsequent superconducting materials.
- 1980's to present: Powder diffraction and Rietveld refinement have seen a
 consistent increase in usage with constantly improving diffractometer technology,
 software capabilities, theoretical understanding, and significantly expanded
 access to synchrotron and neutron facilities. Structure solution from powder
 diffraction data is increasingly routine.



The Problem of Peak Overlap



- Powder diffraction suffers an inherent loss of information, due to the compression of 3D crystalline structure information into 1D.
- For all but the simplest, high symmetry compounds, peak overlap becomes an issue for determining the intensities of individual reflections.




The Problem of Peak Overlap (cont.)

 Before the Rietveld method (1950's and 60's), powder diffraction was most commonly used for qualitative fingerprinting of compounds and mixtures, rather than more quantitative work.

 Quantitative methods tended to use small numbers of isolated peaks to overcome the problem of peak overlap. Inventive, but ultimately limited, methods were developed to estimate intensities

for overlapping peaks.

 Actual structure solution from powder data was exceedingly rare, and focused mainly on high symmetry compounds with well resolved peaks.



The Rietveld Method

- Development of full pattern fitting required (1) sufficient knowledge of diffraction physics and (2) the advent of powerful digital computers.
- Hugo Rietveld (with colleagues at Petten) was the first person to develop (and widely share) computer code for full powder pattern refinement, using data obtained from neutron diffraction:

J. Appl. Cryst. (1969). 2, 65

A Profile Refinement Method for Nuclear and Magnetic Structures

By H. M. RIETVELD

Reactor Centrum Nederland, Petten (N.H.), The Netherlands

(Received 29 November 1968)

A structure refinement method is described which does not use integrated neutron powder intensities, single or overlapping, but employs directly the profile intensities obtained from step-scanning measurements of the powder diagram. Nuclear as well as magnetic structures can be refined, the latter only when their magnetic unit cell is equal to, or a multiple of, the nuclear cell. The least-squares refinement procedure allows, with a simple code, the introduction of linear or quadratic constraints between the parameters.

Rietveld, H.M. Acta. Cryst. 22 (1967) 151-152. Rietveld, H.M. J. Appl. Cryst. 2 (1969) 65-71. van Laar, B. & Schenk, H. Acta Cryst. A74 (2018) 88-92.




What is the Rietveld Method?

- The Rietveld method is a least squares refinement technique used to refine the full powder diffraction pattern.
- The observed data is modeled using a structural model for the phase(s) present, and the difference between the observed (Y_o) and calculated (Y_c) patterns is minimized during refinement:

$$M = \sum w(Y_o - Y_c)^2$$





Rietveld, H.M. Acta. Cryst. 22 (1967) 151-152. Rietveld, H.M. J. Appl. Cryst. 2 (1969) 65-71.

Variable D. A. and The Districted Matter of Onfords New

Young, R.A., ed. The Rietveld Method. Oxford: New York, 1993.

Powder Diffraction Pattern Content

Powder diffraction patterns contain a lot of information!




Figure taken from:


<u>Powder Diffraction, Theory and Practice.</u> Edited by R.E. Dinnebier & S.J.L. Billinge. (RSC Publishing: Cambridge, 2008)

Rietveld Method Applications

- What can we analyze with the Rietveld method?
 - Crystal structure:
 - Lattice parameters, atomic positions, thermal displacement parameters, site occupancies.
 - Phase Composition:
 - Quantitative phase analysis of mixtures of crystalline phases.
 - Estimation of amorphous content with an internal standard.
 - Microstructure:
 - Texture/preferred orientation, crystallite size and strain.
- Most of these properties can be studied as functions of time, temperature, pressure or other variables to understand the in situ or operando behavior of materials.



Applications: Structure Solution & Refinement




 The crystal structure of this pharmaceutical was solved with raw data deposited in the Powder Diffraction File[™] database (PDF-4).

Reid, J.W., Kaduk, J.A. & Vickers, M. Powder Diffraction 31 (2016) 205-210.



Example: Structure of YBa₂Cu₃O_{7-x} (YBCO)

Orthorhombic



Tetragonal





FIG. 2. Structure of YBa₂Cu₃O_{7-x}. (a) The orthorhombic *Pmmm* phase. (b) The tetragonal P4/mmm phase. Note that in the tetragonal phase the oxygen atoms are disordered in the z=0 plane.


- Neutron powder diffraction and Rietveld refinement were critical in the determination of the correct crystal structures of YBCO, the first high temperature superconductor.
- Single crystal methods gave different and incorrect structures due to crystal twinning.




Jorgensen, J.D. et. al. Phys. Rev. B 36 (1987) 3608-3616.

Example: Structure of YBa₂Cu₃O_{7-x} (YBCO)


Orthorhombic




Tetragonal




Oxygen ordering in the low temperature orthorhombic phase creates Cu-O 1-dimensional chains, which are important for superconductivity. Neutrons were critical for determining the oxygen positions and occupancies.







Example: Solving Protein Structures




T₃R₃ human insulin Zn complex Space Group: R3

a = 81.2780(7) Å, c = 73.0389(9) Å

 $V = 417,860(8) \text{ Å}^3 (!)$

1630 atoms (!!)







Von Dreele, R.B. et. al. Acta Cryst. D56 (2000) 1549-1553.

Applications: Phase Quantification

TCP \rightarrow tricalcium phosphate, $Ca_3(PO_4)_2$ HA \rightarrow calcium hydroxyapatite, $Ca_5(PO_4)_3OH$

Reid, J.W. et. al. Mater. Lett. 61 (2007) 3851-3854.








 The influences of small chemistry changes (for instance, impurity concentration in a reactant) can significantly influence the phase composition of the end product.



Example: On-line QA/QC of Cement








$$\begin{split} \text{C3S} &\rightarrow \text{Ca}_{3}\text{SiO}_{5} \\ \text{C2S} &\rightarrow \text{Ca}_{2}\text{SiO}_{4} \\ \text{C4AF} &\rightarrow \text{Ca}_{4}(\text{Al}_{x}\text{Fe}_{1\text{-x}})_{4}\text{O}_{10} \\ \text{C3A} &\rightarrow \text{Ca}_{3}\text{Al}_{2}\text{O}_{6} \end{split}$$

Scarlett, N. V. Y. et. al. Powder Diffraction 16 (2001) 71-80.

THE BRIGHTEST LIGHT IN CANADA | lightsource.ca

Example: Rietveld QPA on Mars

 The CheMin XRD/XRF, one of ten analytical instruments on the Curiosity rover, which landed in the Gale crater in August 2012.



Ca XRF


Co
Co
Si S K Cr
Cr
Co
Si S K Cr

0 10 20 30 40 50 20


Bish, D.L. et. al. IUCrJ 1 (2014) 514-522.



Example: Rietveld QPA on Mars



Mineral	John Klein	Cumberland
Plagioclase	22	22
Fe-forsterite	3	1
Augite	4	4
Pigeonite	6	8
Orthopyroxene	3	4
Magnetite	4	4
Anhydrite	3	1
Bassanite	1	1
Sanidine	1	2
Quartz	0.4†	0.1†
Hematite	0.6†	1
Ilmenite		0.5†
Akaganeite	1	2
Pyrite	0.3†	
Pyrrhotite	1	1
Phyllosilicate	22	18
Amorphous	28	31





Mudstone compositions from two locations on Mars.

Bish, D.L. et. al. IUCrJ 1 (2014) 514-522.



Applications: Crystallite Size and Strain






 Powder diffraction reflection profiles can be used to extract grain size and microstrain information.

> Round robin raw data from: Balzer, D. *et. al.* J. Appl. Cryst. 37 (2004) 911-924.




Applications: Crystallite Size and Shape




• β-Ni(OH)₂ (theophrastite) crystallizes as hexagonal platelets, the average size of the platelets can be estimated with Rietveld refinement employing an anisotropic size broadening model.



Applications: Clays and Disordered Systems



Applications: Clays and Disordered Systems





What is Required for Rietveld Refinement?

- The Rietveld Method is inherently a structure refinement method, **not** a structure solution method.
- Therefore, we need to have a reasonably accurate initial crystal structure model for each phase in the sample.
- We also want to have a well aligned, well characterized diffractometer with known instrument parameters.
- To apply the Rietveld method, we need to understand what parameters control our Bragg reflection (1) positions, (2) intensities and (3) peak shapes and breadth.



Bragg Reflections - Parameters

Table 8.2 Powder diffraction pattern as a function of various crystal structure, specimen and instrumental parameters.^a

Pattern component	Crystal structure	Specimen property	Instrumental parameter
Peak position	Unit cell parameters: $(a, b, c, \alpha, \beta, \gamma)$	Absorption Porosity	Radiation (wavelength) Instrument/sample alignment Axial divergence of the beam
Peak intensity	Atomic parameters $(x, y, z, B, \text{ etc.})$	Preferred orientation Absorption Porosity	Geometry and configuration Radiation (Lorentz, polarization)
Peak shape	Crystallinity Disorder Defects	Grain size Strain Stress	Radiation (spectral purity) Geometry Beam conditioning

^a Key parameters are shown in **bold**. Parameters that may have a significant influence are shown in *italic*.


Table taken from: Pecharsky, V. K. & Zavaliy, P. Y., Fundamentals of

Powder Diffraction and Structural Characterization of

Materials, 2nd edition. (Springer: Berlin, 2009).



Common Powder Diffraction Geometries




Source

synchrotron

Bragg Reflection Positions - Parameters

Reflection Positions depend on:

- X-ray wavelength (λ),
- dimensions of the unit cell (lattice parameters a, b, c, α, β, γ),
- Miller Indices of the diffracting plane in the crystal, &
- systematic errors which depend on the geometry and sample.






Reflection Positions - Bragg's Law


- Bragg's law tells us where a diffraction peak will be located (its 2θ position, in degrees, or °)
- The peak position depends on the X-ray wavelength (λ) and the d-spacing between crystal planes (d_{hkl}).
- The d-spacing (d_{hkl}) depends on the Miller indices of the crystal plane (hkl) and lattice parameters of the unit cell.


$$\lambda = 2d_{hkl}\sin\theta$$

$$2\theta_{calc} = 2\sin^{-1}\left(\frac{\lambda}{2d_{hkl}}\right)$$




Crystal Planes & Interplanar Spacing





- Diffraction is analogous to reflection of X-rays from planes in the unit cell of the crystal.
- The position of peaks in a diffraction pattern depend on the distance (d-spacing) between crystalline planes.



Miller Indices & Interplanar Spacing

Crystallographic planes are described using Miller indices (hkl), which
are derived from the intercepts of the plane with the crystal axes.





Figure courtesy of Michael Gharghouri.


The distance between lattice planes (d-spacing or d_{hkl}) is given by:


$$\begin{aligned} &d_{hkl}\\ &=V[h^2b^2c^2\sin^2\alpha+k^2a^2c^2\sin^2\beta+l^2a^2b^2\sin^2\gamma+2hlab^2c(\cos\alpha\cos\gamma-\cos\beta)\\ &+2hkabc^2(\cos\alpha\cos\beta-\cos\gamma)+2kla^2bc(\cos\beta\cos\gamma-\cos\alpha)]^{-1/2} \end{aligned}$$



Families of Planes







¥




Figure courtesy of Michael Gharghouri.

Systematic Errors (Bragg-Brentano)

$$2\theta_{obs} = 2\theta_{calc} + \Delta 2\theta$$

Sample displacement shift:


$$\Delta 2\theta_{disp} = \frac{-2s}{R} \cos \theta$$


Sample transparency shift:

$$\Delta 2\theta_{trans} = \frac{1}{2\mu R} \sin 2\theta$$


$$R \equiv goniometer\ radius$$








Diffraction Pattern Intensity






Diffraction Pattern Intensity






Background Scattering

- The background of the powder diffraction pattern can be modeled a number of different ways:
 - Empirical functions like the Chebyschev polynomial, cosine Fourier series, power series, etc.
 - Debye function to model amorphous content.
 - Interpolation between fixed or variable background points.





Diffraction Pattern Intensity





Lorentz-polarization Factor

 The Lorentz-polarization (Lp) factor combines geometrical effects including the size of the reciprocal lattice points, radii of the Debye rings, and polarization of the incident beam.


50

$$Lp = \frac{1 - K + K \cdot \cos^2 2\theta \cdot \cos^2 2\theta_M}{\cos \theta \sin^2 \theta}$$

 $K \equiv fractional polarization$

 $2\theta_M \equiv monochromator \ angle$

For a full derivation of the Lorentz-polarization factor, see: Cullity, B.D. <u>Elements of X-ray Diffraction</u>, 2nd Ed. (Addison-Wesley: Reading, 1978).



THE BRIGHTEST LIGHT IN CANADA | lightsource.ca

Lorentz-polarization Factor

 The Lorentz-polarization (Lp) factor combines geometrical effects including the size of the reciprocal lattice points, radii of the Debye rings, and polarization of the incident beam.

$$Lp = \frac{1 - K + K \cdot \cos^2 2\theta \cdot \cos^2 2\theta_M}{\cos \theta \sin^2 \theta}$$

 $K \equiv fractional \ polarization$

 $2\theta_M \equiv monochromator \ angle$

For a full derivation of the Lorentz-polarization factor, see: Cullity, B.D. <u>Elements of X-ray Diffraction</u>, 2nd Ed. (Addison-Wesley: Reading, 1978).

GSAS2 polarization ('Polariz' instrument parameter):

Instrument	Polariz.				
Unpolarized					
(no mono)	0.5				

Cu Kα with Graphite mono 0.7-0.8

Synchrotron 0.9-1.0



Sample Absorption (Bragg-Brentano)

 The diffracted intensity is reduced by absorption in the specimen according to the transmission coefficient:

$$A = \frac{1}{V} \int e^{-\mu l} dV$$

$$\lim_{l = \text{total path length}} \mu \equiv \text{linear absorption}$$

$$\text{coefficient}$$

- For Bragg-Brentano geometry, there are two limiting cases:
 - 1. High μ (&/or t) $\rightarrow A = \frac{\mu}{2}$ (constant, independent of 20)

2. Low
$$\mu$$
 (&/or t) $\rightarrow A = \frac{1 - e^{\frac{-2\mu t}{\sin \theta}}}{2\mu}$ $t \equiv sample thickness$




Sample Absorption (Debye-Scherrer)

 For Debye-Scherrer geometry, the absorption correction depends on μR (R is the radius of the capillary):

$$A = e^{\left[-k_0 \mu R - k_1 (\mu R)^2 - k_2 (\mu R)^3 - k_3 (\mu R)^4\right]}$$

- $0 < \mu R < 0.5$ \rightarrow Low absorption, no correction required.
- 0.5 < μR < 1 \rightarrow Normal absorption, may need correction for precise thermal parameters.
- 1 < μ R < 2.5 \rightarrow High absorption, correction recommended for analysis.
- 2.5 < μ R \rightarrow Too high! Re-think your sample preparation.
- APS beamline 11-BM absorption guide & calculator: https://11bm.xray.aps.anl.gov/absorption.html

Diffraction Pattern Intensity






Scale Factor

• The scale factor (S_p) is proportional to the quantity of each phase, p, present in a mixture, and can be used to estimate the crystalline phase composition, W_p (weight fraction):

$$W_p = \frac{S_p(ZMV)_p}{\sum_i S_i(ZMV)_i}$$

 $Z \equiv formula units per unit cell$ $M \equiv molecular mass$ $V \equiv unit cell volume$





Scale Factor


• The scale factor (S_p) is proportional to the quantity of each phase, p, present in a mixture, and can be used to estimate the crystalline phase composition, W_p (weight fraction):

$$W_p = \frac{S_p(ZMV)_p}{\sum_i S_i(ZMV)_i}$$

 The relative intensity of crystalline phases is often compared to Corundum (Al₂O₃):

For Si:
$$I/I_C = ~4.5$$






Absorption – Phase Effects

- For Bragg-Brentano geometry, surface roughness and porosity effects can considerably influence reflection intensities:
 - Suortti, P. J. Appl. Cryst. 5 (1972) 383-400.
 - Pitschke, W., Hermann, H., & Mattern, N. Powder Diffraction 8 (1993) 74-83.
 - Pitschke, W., Mattern, N., & Hermann, H. Powder Diffraction 8 (1993) 223-228.
- Results for quantitative phase analysis (QPA) of multiphase mixtures can be strongly influenced by absorption contrast between different phases, called microabsorption:
 - Brindley, G.W. Philosophical Magazine 3 (1945) 347-369.
 - Scarlett, N. V. Y., et al. J. Appl. Cryst. 35 (2002) 383-400.
 - Scarlett, N. V. Y. & Madsen, I.C. Powder Diffraction 33 (2018) 26-37.



Absorption – Phase Effects

- Microabsorption, or contrast in a mixture of high and low absorbing phases, is often the biggest obstacle encountered for accurate quantitative phase analysis (QPA).
- High absorbing phases have diffraction restricted to the particle surface and tend to be underestimated.
- Low absorbing phases diffract from the entire volume and tend to be overestimated.






Figure courtesy of Pamela Whitfield.

Brindley, G.W. Philosophical Magazine 3 (1945) 347-369. Scarlett, N. V. Y., et al. J. Appl. Cryst. 35 (2002) 383-400. Scarlett, N. V. Y. & Madsen, I.C. Powder Diffraction 33 (2018) 26-37.




Mitigating Microabsorption

- Microabsorption can be minimized by:
 - Making sure your sample has been very well ground or micronized to obtain the smallest possible particle sizes (the degree to which microabsorption is an issue is proportional to the product of the linear absorption coefficient and particle size, µD).
 - Using higher energy radiation (synchrotron, if available); absorption decreases with increasing X-ray energy.
 - Using neutrons (if available); not always easy to access, but the gold standard solution for microabsorption.
- Brindley devised a correction based on knowing μD (i.e. average particle sizes) for each phase which can work in ideal cases, but is typically impractical.



Diffraction Pattern Intensity





Structure Factor

 The structure factor relates the atomic positions, atomic species (via the atomic scattering factor) and thermal displacement (via the thermal factor) to the intensity of individual hkl reflections:

Displacement (Debye-Waller) Factor

Site Occupancy
$$F_{hkl} = \sum_{j}^{\downarrow} \sum_{N_{j}}^{\downarrow} f_{j} e^{-B_{j} \left(\frac{\sin \theta}{\lambda}\right)^{2}} e^{2\pi i (hx_{j} + ky_{j} + lz_{j})}$$
Atomic coordinates

Atomic Scattering Factor

$$F_{hkl} = \frac{amplitude\ scattered\ by\ the\ atoms\ in\ the\ unit\ cell}{amplitude\ scattered\ by\ a\ single\ electron}$$



Atomic Scattering Factor

$$f = \frac{amplitude\ scattered\ by\ an\ atom}{amplitude\ scattered\ by\ a\ single\ electron}$$

- Light elements scatter Xrays relatively poorly.
- The intensities of X-ray diffraction peaks decrease rapidly with increasing diffraction angle (2θ).




Figure taken from: Copley, J.R.D. *Natl. Inst. Stand. Technol. Spe. Pub.* 960-2 (2001).



Comparison of Atomic Form Factors





Figure courtesy of John Faber

Tb₂Ti₂O₇



Comparison of Atomic Form Factors






Figure courtesy of John Faber



Atomic Scattering Factor

$$f = \frac{amplitude\ scattered\ by\ an\ atom}{amplitude\ scattered\ by\ a\ single\ electron}$$

- Light elements scatter Xrays relatively poorly.
- The intensities of X-ray diffraction peaks decrease rapidly with increasing diffraction angle (2θ).




Figure taken from: Pecharsky, V. K. & Zavaliy, P. Y., <u>Fundamentals of Powder Diffraction and Structural Characterization of Materials</u>, 2nd edition. (Springer: Berlin, 2009).




Displacement Parameter

 The displacement parameter reflects thermal and vibrational motion in the atoms from their equilibrium positions which attenuates the reflection intensities:

$$e^{-B_j\left(\frac{\sin\theta}{\lambda}\right)^2}$$

$$\boldsymbol{B_j} = 8\pi^2 u_j^2 = 8\pi^2 \boldsymbol{U_j}$$

• B_j is called the Debye-Waller factor and U_j is the root mean squared thermal displacement of the atom.



Reflection Multiplicity

The multiplicity reflects
 the number of equivalent
 planes (or equivalent
 grain orientations to
 diffract) belonging to a
 set of hkl indices.




Figure courtesy of Michael Gharghouri.

48 - {hkl}

System	hkl	hhl	hh0	0kk	hhh	hk0	h0l	0kl	h00	k00	001
Cubic	48*	24	12	12	8	24*	24*	24*	6	6	6
Tetragonal	16*	8	4	8	8	8*	8	8	4	4	2
Hexagonal	24*	12*	6	12	12	12*	12*	12*	6	6	2
Orthorhombic	8	8	8	8	8	4	4	4	2	2	2
Monoclinic	4	4	4	4	4	4	2	4	2	2	2
Triclinic	2	2	2	2	2	2	2	2	2	2	2

Asterisk (*) indicates non-equivalence of planes may reduce this number by half in some circumstances.



Reflection Profile Functions

 X-ray diffraction reflections tend to be mixtures (mixing parameter η) of Gaussian (G) and Lorentzian (L) distributions which are typically combined in what is called a pseudo-Voigt (pV) function:

$$pV(2\theta) = \eta L(2\theta) + (1 - \eta)G(2\theta)$$

$$G(2\theta) = \left[\frac{2}{\Gamma_G}\right] \sqrt{\frac{\ln 2}{\pi}} e^{\frac{-4 \ln 2(2\theta - 2\theta_{hkl})^2}{\Gamma_G^2}}$$

$$L(2\theta) = \frac{\frac{2}{\pi \Gamma_L}}{1 + \frac{4(2\theta - 2\theta_{hkl})^2}{\Gamma_L^2}}$$




Figure taken from: Kaduk, J.A. & Reid, J. Powder Diffraction 26 (2011) 88-93.



Reflection Profile Functions

 A parameterization of the pseudo-Voigt called the Thompson-Cox-Hastings pseudo-Voigt (TCH-pV) model (Thompson, P. et al. *J. Appl. Cryst.* 20 (1987) 79-83) is commonly used in Rietveld software because it makes it relatively easy to relate the full width at half maximum (FWHM or Γ) parameters to instrument resolution and specimen broadening effects:

$$\Gamma_G^2 = U \tan^2 \theta + V \tan \theta + W + \frac{P}{\cos^2 \theta}$$

'Mostly' instrument broadening

$$\Gamma_L = \frac{X}{\cos \theta} + Y \tan \theta$$

'Mostly' sample broadening


The 1/cos θ coefficients (P, X) tend to correlate to size broadening,
 while the tan θ coefficients (U, Y) tend to correlate to strain broadening.




Preferred Orientation/Texture












Single Crystal

Textured Polycrystal


Random Powder




Preferred Orientation/Texture












Single Crystal



Textured Polycrystal



Random Powder




Preferred Orientation/Texture

- Straightforward cases of preferred orientation, typically platelet or needle morphologies, can be adequately refined using the March-Dollase model:
 - Dollase, W. A. J. Appl. Cryst. 19 (1986) 267-272.
- More complicated cases require a general orientation distribution function (ODF) approach using spherical harmonics:
 - Von Dreele, R. B. J. Appl. Cryst. 30 (1997) 517-525.
 - Bunge, H. J., Textures and Microstructure 29 (1997) 1-26.



Diffraction Pattern Intensity





Summary

- Powder diffraction is a comprehensive technique for studying crystalline materials with crystal sizes ranging from microns (10⁻⁶ m) to nanometers (10⁻⁹ m), across many scientific fields (mineralogy, advanced materials, pharmaceutical science, catalysis, forensics, etc.).
- The Rietveld method is not a structure solution method, it's a refinement method. A reasonable starting model is needed for each phase in your sample.
- To make the most of powder diffraction and Rietveld refinement, you need a basic understanding of the physical underpinnings of the powder diffraction pattern.

Acknowledgements

A sincere thank you to Jim Kaduk, John Faber,
Michael Gharghouri, Pam Whitfield, Denis Spasyuk,
Saeed Ghazani & Alejandro Marangoni for the
liberal use of their figures, ideas and knowledge.



Further Reading

Pecharsky, V.K. & Zavalij, P.Y. <u>Fundamentals of Powder Diffraction and Structural Characterization of Materials</u>, 2nd Ed.

Springer: New York, 2009.

Dinnebier, R.E. & Billinge, S.J.L., ed. <u>Powder Diffraction, Theory and Practice</u>.

RSC: Cambridge, 2009.

Young, R.A., ed. <u>The Rietveld Method</u>.
 Oxford: New York, 1993.

Warren, B.E. X-ray Diffraction.
 Dover: New York, 1990.

 Klug, H.P. & Alexander, L.E. X-ray Diffraction Procedures for Polycrystalline and Amorphous Materials, 2nd Ed.

Wiley: New York: 1974.