Drill three holes in the centre of the angle iron as shown here:

