

Leave 20mm of shaft exposed and allow to dry.