Fasten the generator to the base plate assembly using $\frac{1}{2}$ "x1.5" bolts, nuts and washers.

