The holes to mount our motor are  $\frac{1}{2}$  inch diameter (approx 12.5mm), so we need to drill 4 holes to match. The hole in the middle is just so that the wires can pass through.

