



## READ ERROR FROM IR SENSORS





LINE	FOLLOWII	MECHATRONICS PROJECT					
Func.	Full name	Sign	Date		Quantity	Weight	Scale
Designer	Tr.A.Quoc	·	20/12				
	H.B.Loc	1		Algorithm flowchart			
	P.Đ.K.Nguyen	· 		_	Sheet: 3	Total sheets: 4	
	Ng.H.Minh	1			HCMC University of Technolog		
Instruct.	V.T.Quan	1			Faculty of Mechanical Engineering		
		1					
Approve	V.T.Quan	1			Lilyineering		