LORE = Saffey and Professionalism technicians need the light tools to do their Job. They include PC toolkit, mobile device toolkit, voltmeters, and circuit tester, carry multiple thumb drives Trouble shooting theory Step 1: Identify the problem Step 2: Establish a theory of probable cause Stop 3: test theory to determine cause Stop 4: Establish plus of Adian to resolve & implement Solution Step5: Verify full system functionally & implement preventutive measures Step 6: Document findings , actions, & outcomes