

Log Pattern Classifier Report

Total Events: 35

Flaps: 2

Anomalies: 1

Correlations: 3

Overall Severity: CRITICAL

Detected Incidents

Type: multi_port_failure

Severity: critical

Description: Possible switch reset or fabric issue

Time: 2026-03-05 18:16:10.120000

Type: link_instability

Severity: critical

Description: Port error leading to restart

Time: 2026-03-05 18:16:11

Type: congestion_failure

Severity: critical

Description: High packet loss leading to link failure

Port: Ethernet1

Incident Narrative

=== Incident Summary ===

1. Multiple ports went down simultaneously. This indicates a possible switch reset or fabric issue.
2. A port error was followed by link failure and system restart. This suggests link instability.
3. High packet loss detected on Ethernet1 leading to link failure. This indicates congestion-related issues.

Overall Severity: CRITICAL