

SYNTHETIC DEMO - WCR - OFF-04

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-04; Event: cementing_issue; Formation: TIPAM_A; MD: 2410.00-2415.00 m; TVD: 2410.00 m; Severity: warning; Observation: Historical synthetic cementing_issue reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - WCR - OFF-04

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-04; Event: stuck_pipe; Formation: TIPAM_A; MD: 2470.00-2475.00 m; TVD: 2470.00 m;
Severity: warning; Observation: Historical synthetic stuck_pipe reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - WCR - OFF-04

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-04; Event: stuck_pipe; Formation: TIPAM_A; MD: 2510.00-2515.00 m; TVD: 2510.00 m;
Severity: warning; Observation: Historical synthetic stuck_pipe reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - WCR - OFF-04

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-04; Event: mud_loss; Formation: TIPAM_A; MD: 2482.00-2487.00 m; TVD: 2482.00 m;
Severity: warning; Observation: Historical synthetic mud_loss reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - WCR - OFF-04

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-04; Event: stuck_pipe; Formation: TIPAM_A; MD: 2506.00-2511.00 m; TVD: 2506.00 m;
Severity: warning; Observation: Historical synthetic stuck_pipe reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - WCR - OFF-04

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-04; Event: kick_or_overpressure; Formation: TIPAM_A; MD: 2530.00-2535.00 m; TVD: 2530.00 m; Severity: warning; Observation: Historical synthetic kick_or_overpressure reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h