




MAX POWER DRIVER REPLACEMENT (CONT-OPTIMIZED) A-1500-2

MAX POWER DRIVER REPLACEMENT (CONT-OPTIMIZED) A-1500-3

MAX POWER DRIVER REPLACEMENT (CONT-OPTIMIZED) A-1500-3

CAUTION: +50V DC and 0.3VAC G.L. present on this board