

Machine Design 2(2+0)

Theory-

Meaning of design, Phases of design, design considerations. Common engineering materials and their mechanical properties. Types of loads and stresses, theories of failure, factor of safety, selection of allowable stress. Stress concentration.

Elementary fatigue and creep aspects. Cotter joints, knuckle joint and pinned joints, turnbuckle. Design of welded subjected to static loads. Design of threaded fasteners subjected to direct static loads, bolted joints loaded in shear and bolted joints subjected to eccentric loading. Design of shafts under torsion and combined bending and torsion. Design of keys. Design of muff, sleeve, and rigid flange couplings. Design of helical and leaf springs. Design of flat belt and V-belt drives and pulleys. Design of gears. Design of screw motion mechanisms like screw jack, lead screw, etc. Selection of anti-friction bearings.

Suggested Readings-

- Jain R K. 2013. Machine Design. Khanna Publishers, 2-B Nath Market, Nai Sarak, New Delhi.
- Khurmi R S and Gupta J K. 2014. A Text Book of Machine Design. S. Chand & Company Ltd., New Delhi