#### **Sheet Forming Processes**


#### **Basic Categories**

Shearing

Bending

Drawing


#### Standard Punching Operation




#### **Conventionally Sheared Surface**




#### Fineblanking Process




#### Fineblanked Part




#### Power Shear




## Piercing vs. Blanking




## Piercing, Lancing and Blanking



#### Blanking Punch Design




## 5-Station Progressive Piercing, Forming and Cut-off Punch and Die



## Stages of 11-Station Progressive Punch and Die




#### Bar Folder




#### Press Brake








#### **Bent Sheet Profiles**




## Dies Forming a Rolled Bead









## **Roll Bending**






#### Bend Sheets into Shapes




#### Forming a Box Channel




#### **Sheet Metal Seaming**



#### Straightening Sheets and Strips



#### Forming Sheet by Spinning




## Forming a Reflector by Spinning







## **Shear Forming**




#### Stretch Forming




#### **Deep Drawing**




## Metal Flow in Drawing




# Piercing, Blanking, Drawing and Trimming




## **Hydroforming Sheets**




## **Hydroforming Tubes**




#### Cross-section of Formed Tube




#### Formed Tubes in Auto Bodies



## **Hot Drawing**



## Ironing



#### **Embossing**

