

Add-on 3
101

Boulder County Health Department Air Inspection Report

COUNTY NUMBER
013

SOURCE NUMBER
124

EMISSION POINTS
000

DATE
5/14/96

COMPANY: Southwestern Portland Cement

SITE LOCATION: 5134 Ute Highway, Lyons CO

CONTACT PERSON: Steve Mossberg

TELEPHONE NUMBER: 823-2113

INSPECTION TYPE: Major Routine

HOURS REQUIRED: 1.5 hrs

Prep/Travel: .5

Inspection: .5

Report/EIS: .5

INSPECTOR: Bonnie Greenwood

COUNTY: Boulder

TIME: 3:30 pm

PERMIT NUMBER: Grandfathered

COMPLIANCE STATUS: In Compliance

This was a minor source inspection as per CDPHE/APCD, BCHD 1996 Air Contract. The inspection was done with John Lohr and Steve Mossberg of Southwestern Portland Cement. Southwestern Portland Cement purchased the quarry five years ago, at which time they submitted a change of ownership to CDPHE. The quarry is mined 2 days a week for 8 hours a day, for six months a year (416 hours per year). The pit is located on the southwest side of highway 66 just before entering the town of Lyons.

The quarry mines silica sandstone. There is a primary crusher (1964 Pioneer) located in the pit for preliminary crushing of silica to a 4" diameter. The design rate of the crusher is approximately 300 tons/hour. The crusher is equipped with a spray for dust control, and is powered with a 150 hp diesel generator. No dust was noted from any haul roads at the time of the inspection.

Blasting is done about once per month. Water and detergent are used during the drilling process. The total throughput for 1995 was 27,168 tons of rock.

STATUS: In Compliance. No significant change in emissions.

RECEIVED
JUN 14 1996
AIR POLLUTION CONTROL DIVISION
STATIONARY SOURCES PROGRAM

SOUTHDOWN, IN
LYONS PLANT

OPERATIONS SUMMARY FOR
PLANT QUARRY (A, C, E PITS)
DECEMBER 1995

RECEIVED

JUN 28 1996

	1ST RIDGE	3RD RIDGE	3-4 RIDGE	4TH RIDGE	WEATHER ROCK	TOTAL TONS
1	0	0	0	0	0	0
2	0	0	0	0	0	0
3	0	0	0	0	0	0
4	0	0	0	0	(32,040)	(32,040)
5	2,380	0	0	0	0	2,380
6	0	0	0	0	0	0
7	1,275	0	0	0	0	1,275
8	1,870	9,435	0	0	0	11,305
9	0	0	0	0	0	0
10	0	0	0	0	0	0
11	0	0	0	0	0	0
12	0	0	0	0	0	0
13	0	0	0	0	0	0
14	0	0	0	0	0	0
15	7,395	0	340	0	0	7,735
16	0	0	0	0	0	0
17	0	0	0	0	0	0
18	0	0	0	0	0	0
19	0	0	0	0	0	0
20	0	10,625	0	0	0	10,625
21	0	0	0	0	0	0
22	6,035	0	0	0	0	6,035
23	0	0	0	0	0	0
24	0	0	0	0	0	0
25	0	0	0	0	0	0
26	0	0	0	0	0	0
27	2,975	4,505	0	0	0	7,480
28	0	0	0	0	0	0
29	7,310	5,850	0	0	0	13,260
30	3,570	0	0	0	0	3,570
31	(38,930)	(56,840)	297	0	0	(95,473)
	(6,120)	(26,325)	637	0	(32,040)	(63,848)
YEAR	460,617	238,705	17,637	0	(32,040)	684,919

SOUTHDOWN, INC.
LYONS PLANT

OPERATIONS SUMMARY FOR
PURCHASED MATERIALS
DECEMBER 1995

PAGE 2 OF 2

	COAL	FUEL OIL	USED TIRES	BAGS	PALLETS	RETURN PALLETS	WHITE CEMENT
1	0	0	0	0	0	0	0
2	0	0	0	0	0	0	0
3	0	0	0	0	0	0	0
4	800	0	0	0	0	0	0
5	400	0	0	0	0	0	0
6	0	0	0	0	0	0	0
7	0	0	0	0	0	0	0
8	900	0	0	0	0	0	0
9	0	0	0	0	0	0	0
10	0	0	0	0	0	0	0
11	0	0	0	0	0	0	0
12	800	0	0	0	0	0	0
13	1114.85	0	0	0	0	0	0
14	0	0	0	0	0	0	0
15	600	0	0	0	0	46	0
16	0	0	0	0	0	0	0
17	0	0	0	0	0	0	0
18	400	0	0	0	0	0	0
19	900	0	0	0	0	0	0
20	900	0	0	0	0	0	0
21	400	0	0	0	0	0	0
22	832	0	0	0	0	0	0
23	0	0	0	0	0	0	0
24	0	0	0	0	0	0	0
25	0	0	0	0	0	0	0
26	0	0	0	0	0	0	0
27	0	0	0	0	0	0	0
28	0	0	0	0	0	0	0
29	0	0	0	0	0	0	0
30	0	0	0	0	0	0	0
31	0	0	0	0	0	0	0
	8,047	0	0	0	0	46	0
YEAR	76,752	0	0	243,926	3,500	1,001	0

SOUTHDOWN, IN
LYONS PLANT

OPERATIONS SUMMARY FOR
CRUSHER
DECEMBER 1995

	1ST RIDGE	3RD RIDGE	3-4 RIDGE	4TH RIDGE	WEATHER ROCK	TOTAL TONS	CRUSHER HOURS	RATE TPH	CUM %UPTIME
1	1,452	793	0	0	45	2,290	21.50	106.51	0.896
2	1,202	868	0	0	148	2,218	22.50	98.58	0.917
3	1,512	707	0	0	450	2,669	21.00	127.10	0.903
4	1,575	1,355	0	0	3	2,933	21.50	136.42	0.901
5	1,290	577	0	0	46	1,913	17.50	109.31	0.867
6	399	571	0	0	30	1,000	7.50	133.33	0.774
7	1,690	536	0	0	257	2,483	20.50	121.12	0.786
8	1,199	978	0	0	191	2,368	19.00	124.63	0.786
9	1,969	1,007	0	0	0	2,976	21.00	141.71	0.796
10	1,517	781	0	0	160	2,458	19.00	129.37	0.796
11	1,326	864	0	0	190	2,380	18.50	128.65	0.794
12	1,486	710	0	0	200	2,396	20.00	119.60	0.797
13	537	490	545	0	0	1,572	11.50	136.70	0.772
14	1,385	555	336	0	0	2,276	17.50	130.06	0.769
15	1,705	974	0	0	0	2,679	18.50	144.81	0.769
16	1,155	910	377	0	0	2,442	19.00	128.53	0.771
17	1,609	853	422	0	0	2,884	20.50	140.68	0.776
18	1,272	1,144	0	0	0	2,416	21.00	115.05	0.781
19	1,840	683	0	0	216	2,739	20.50	133.61	0.785
20	1,550	1,115	0	0	0	2,665	18.00	148.06	0.783
21	607	356	0	0	228	1,191	11.00	108.27	0.768
22	1,727	1,207	0	0	0	2,934	20.50	143.12	0.772
23	2,006	766	0	0	0	2,772	22.00	126.00	0.778
24	973	718	0	0	342	2,033	14.00	145.21	0.770
25	1,036	658	0	0	0	1,694	16.00	105.88	0.766
26	1,209	114	0	0	0	1,323	11.50	115.04	0.755
27	995	1,070	0	0	465	2,530	17.50	144.57	0.754
28	1,966	314	0	0	0	2,300	16.00	143.75	0.751
29	725	921	0	0	0	1,646	11.00	149.64	0.741
30	1,735	805	0	0	416	2,956	20.50	144.20	0.744
31	3,290	2,159	0	0	249	5,698	20.50	277.95	0.748
	43,959	25,559	1,680	0	3,636	74,834	556.50	134.47	
YEAR	451,375	255,902	19,123	0	57,769	784,169	6,166.40	127.17	

5-11-56

OPERATIONS REPORT

PAGE 4

CEMENT HOUR	DIS TEMP	F. MILL KW/TON	CALCULATED CLINKER PROD	CLINKER PRODUCED	CLINKER EQUIV TON	BELT SC CLINKER	COAL TON/HR
0	126.50		47.50	48.55	6.50	49.7	12.77
1	126.50		43.10	44.04	6.53	54.4	12.49
2	126.50		41.50	42.40	6.50	53.3	12.31
3	127.25		40.40	47.25	6.42	52.6	12.31
4	130.25		50.30	51.52	6.38	52.8	11.43
5	134.00		51.30	53.23	6.30	52.2	12.49
6	135.25		37.10	36.57	6.23	43.9	8.77
7	136.25		43.70	44.30	6.55	39.2	8.75
8	136.00		47.50	43.32	6.50	41.5	6.16
9	136.75		50.20	53.41	6.53	52.9	6.53
10	137.75		46.50	50.81	6.75	52.8	6.61
11	137.50		50.70	51.70	6.60	53.3	6.58
12	138.00		53.90	55.14	6.81	51.8	6.52
13	137.25		54.00	55.40	6.81	51.9	6.52
14	136.75		50.50	53.09	6.80	53.9	6.53
15	138.25		51.80	53.00	6.80	52.2	6.55
16	140.00		50.40	51.59	6.81	52.2	6.47
17	140.25		46.70	50.80	6.80	13.1	6.19
18	140.00		53.50	54.79	6.81	14.7	6.50
19	139.75		43.70	49.59	6.81	49.3	6.33
20	139.50		47.90	43.90	6.90	23.4	6.33
21	139.00		46.30	47.25	6.90	46.9	6.41
22	139.25		49.40	50.37	6.90	51	6.52
23	138.75		56.10	57.40	6.81	53.9	6.41
DAY TOTALS		3257.25	1182.10	1203.51		1103.73	194
HOURLY AVERAGE		135.72	49.25	50.35	6.56		8.67

SOUTHDOWN, INC.

DAILY PRODUCTION REPORT

DATE: 5-11-96

LYONS F

FINISH MILL	TYPE I	TYPE II	TYPE II LA	TYPE V	MASON	PRODUCT	II LA	TOTAL
TONS PRODUCED		1954						1954
HOURS		24						24
GYP SUM USED		111						111
GRIND AID								
AIR ENTRAIN								
CLINKER I								
CLINKER II		1693						1693
CLINKER II LA								
CLINKER II Original Clinker		150						150

DOWNTIME

REASON

No Downtime.

KILN	CLINKER PRODUCED	TYPE I	TYPE II	TYPE II LA	TYPE V	TOTALS
TONS USED	HRS		408	800		1208
HRS OPERATED	COAL TONS		8	16		24
COAL MOISTURE	OIL GALS		66	128		194
TOTAL TONS OF CLINKER PRODUCED	TIRES TONS					
	GAS MCF		1008	2032		3040

DOWNTIME

REASON

No Downtime.

RAW MILL	TYPE I	TYPE II	TYPE II LA	TYPE V	TOTAL MILL PRODUCTION	TONS
HOURS			22		2609	
1ST RIDGE			1387			
3RD RIDGE			940			
3-4 RIDGE						
4TH RIDGE						
WEATHERED			186			
SILICA			77			
IRON ORE			19			
ALUMINA						

DOWNTIME

REASON

Out of 3rd ridge.

CRUSHER	1ST RIDGE	3RD RIDGE	3-4 RIDGE	4TH RIDGE	WEATHER	SILICA	IRON	GYP SUM	ALUMINA	
TONS CRUSHED	1918	800			309	207				
BENEFICIATED										
HRS OPERATED	CRUSHER	DRYER	LOADER	FUEL USED	GAS MCF	COAL TONS	WASTE DUST	WET	DRY	
	21.5	21.5	22		612					360 Tons

DOWNTIME

REASON

Rock changes.

SHI

100 ton
PHYS INV CORR
1308

SOUTHDOWN, INC.
LYONS PLANT
DAILY REPORT

DATE: MAY 11, 1996

MATERIALS	TONS MADE		TONS USED		INVENTORY
	TONS DAY	TONS MONTH	TONS DAY	TONS MONTH	
Q 1ST RIDGE	0	18,316	1,918	14,280	75,208
R 3RD RIDGE	0	8,330	800	11,377	26,790
R 3-4 INTERRIDGE	0	0	0	0	259
R 4TH RIDGE	0	0	0	0	0
Y WEATHERED	0	0	0	815	50,301
TOTAL ROCK	0	26,646	2,718	26,472	152,558
CRUSHED ROCK	2,446	23,825	2,513	23,900	1,429
P SILICA	0	420	77	640	9,081
U IRON ORE	0	0	19	171	14,453
R CLAY	0	0	0	0	0
C COAL	0	1,000	194	3,011	3,432
H FUEL OIL	0	0	0	0	0
A GAS	3,652	13,627	3,652	13,627	0
S TIRES	0	0	0	0	0
E GYPSUM	0	632	111	1,314	4,227
D BAGS	0	0	0	3,040	142,389
PALLETS	0	49	0	82	1,178
TOTAL KILN FEED	2,609	24,711	2,263	23,986	3,471
C TYPE I	0	0	0	0	2,908
L TYPE II	508	8,318	1,843	17,981	51,281
K TYPE II LA	800	5,546	0	0	20,647
R TYPE V	0	0	0	0	801
TOTAL KILN	1,308	13,864	1,843	17,981	75,637
F TYPE I	0	0	0	467	773
I TYPE II	1,954	19,061	128	17,368	6,811
I TYPE II LA	0	0	52	1,045	8,937
I TYPE V	0	234	0	745	1,466
S MASONRY	0	0	0	172	1,107
H PRODUCT	0	0	0	475	1,109
E TYPE III LA	0	0	25	2,003	1,313
TYPE IP	0	0	0	0	698
D TOTAL CEMENT	1,954	19,295	206	22,275	22,214
FLORENCE	25	1,713	0	1,861	80
AMARILLO, TX	0	0			
DUST HAULED			360	3,392	
KILN DUST SOLD			50	369	

F MMBTU	COAL	GAS	TIRES	TOTAL	PER TON
U	DAY	DAY	DAY		
E KILN	4,346	3,283	0	7,629	5.83
L DRYER	0	661	0	661	0.25

	HOURS		%UPTIME	TONS PER	
	DAY	MONTH	MONTH	DAY	HOUR
CRUSHER	21.5	203.5	0.771	2,718	126.42
RAW MILL	22.0	216.0	0.818	2,513	114.23
KILN	24.0	257.0	0.973	1,308	54.50
FINISH MILL	24.0	220.5	0.835	1,954	81.42

SOUTHDOWN, INC.
LYONS PLANT
SUMMARY DAILY REPORT

	05/11/96 -----	MONTH TO DATE -----	1996 PLAN -----	INVENTORY -----
RAW GRIND:				
TONS	2,609	24,711		3,471
HRS	22	216		
CLINKER BURN:				
TONS	1,308	13,864		75,637
HRS	24	257		
AVG PER HOUR	55	54		
AVG PER 24 HR. DAY	1,308	1,295		
FINISH GRIND:				
TONS	1,954	19,295		22,293
HRS	24	221		
AVG PER HOUR	81	88		
SALES:				
TONS	181	20,562		
FLORENCE	0	1,861		
	-----	-----		
	181	22,423		

RECEIVED

JUN 28 1996

APPROVED BY: _____
SIGNATURE: _____

	TODAY RECEIVED	MONTH RECEIVED	SALES TODAY	SALES MONTH	YTD
TYPE K CEMENT	0.00	0.00	0.00	0.00	0.00
SHALE SALES	0.00	0.00	0.00	0.00	118.45
MTN. CEMENT CLINKER SALES I/II	0.00	0.00	0.00	0.00	6458.75

013-003

Boulder County Health Department Complaint Report

3450 Broadway
Boulder, Colorado 80304
(303) 441-1180 Fax (303) 441-1289

Monday, July 08, 1996

Report # 101

Complainant Information

Name of Caller: John Barth

Phone Number: 543-8702

Second Phone: _____

Date of Call: 6/13/96

Time of Call: 1:05:00 AM

Responsible Party Information

Source #: 003

Owner: Southwestern Portland Cement

Address: 5134 Ute Hwy

City: Lyons,

State: CO

Zipcode: _____

Phone: 823-2113

Contact Person: Steve Mossberg

Nature of Complaint:

The cement plant is very dusty today. Winds are relatively calm. There are dump trucks blowing dust and some dust may be from process.

Call Received By: Bonnie Greenwood

Report of Investigation:

6/13/96: Spoke with Mr. Barth and told him that I had just been to the facility the day before and I had just completed a yearly inspection in May. They (SWP) had applied Magnesium Chloride that week which had really improved the major roads into the plant and quarry. They have done major improvements to many areas that had been problems in the past and inspection found them in compliance. I told him that we could not get an inspector out that afternoon but that I would call SWP to find out if there had been any upsets or malfunctions (which there were not). This is probably dust from the mining or reclaiming which is easily kicked up by winds and storms.

BCHD Representative: Bonnie Greenwood

Hours Spent On Complaint:

1