

AIR POLLUTION CONTROL - FIELD INSPECTION SHEET

COUNTY NUMBER	SOURCE NUMBER	EMISSION POINTS	DATE
<u>0220</u>	<u>003</u>	<u>000</u>	<u>11/16/90</u>
COMPANY: <u>Southwestern Portland Cement Co</u>		INSPECTOR: <u>D. Niemiec</u>	
SITE LOCATION: <u>2 miles SE of Lyons</u>		COUNTY: <u>Boulder</u>	
CONTACT PERSON: <u>Randy Wiley</u>		TIME: <u>2:51 - 3:00 pm</u>	
TELEPHONE NUMBER: <u>534-4206</u>		EIS UPDATE: <u>NO</u>	
INSPECTION TYPE: <u>Surveillance - Major</u>		PERMIT NUMBER: <u>NA</u>	
HOURS REQUIRED: <u>1.35</u>			
Prep/Travel: <u>0.75</u>			
Inspection: <u>0.10</u>		COMPLIANCE STATUS: <u>YES</u>	
Report/EIS: <u>0.50</u>			

Emission Points Subject to NSPS?: Yes

Unannounced surveillance inspection.

Haul roads were recently wetted. There was no fugitive dust noted being transported off-property. Opacity was 0% at the point sources.

RECEIVED

DEC 19 1990

AIR POLLUTION CONTROL DIVISION
STATIONARY SOURCES PERMITTING

AIR POLLUTION CONTROL - FIELD INSPECTION SHEET

COUNTY NUMBER	SOURCE NUMBER	EMISSION POINTS	DATE
<u>0220</u>	<u>003</u>	<u>001</u>	<u>6/19/91</u>
COMPANY: <u>Southwestern Portland Cement</u>		INSPECTOR: <u>D. Niemiec</u>	
SITE LOCATION: <u>2 miles SE of Lyons</u>		COUNTY: <u>Boulder</u>	
<u>Lyons, CO</u>			
CONTACT PERSON: <u>Stewart Tomlinson</u>		TIME: <u>8:15 am</u>	
TELEPHONE NUMBER: <u>823-6685</u>		EIS UPDATE: <u>NO</u>	
INSPECTION TYPE: <u>Complaint - Major Source</u>		PERMIT NUMBER: <u>NA</u>	
HOURS REQUIRED: <u>0.50</u>			
Prep/Travel: <u>0.00</u>			
Inspection: <u>0.00</u>		COMPLIANCE STATUS: _____	
Report/EIS: <u>0.50</u>			

Emission Points Subject to NSPS?: _____

The Boulder County Health Department received a fax complaint from Brian Andreja on Sunday 6/16/91, concerning dust being generated from the kiln dust being applied in the quarry.

I called Randy Wiley of Southwestern on Monday morning to inquire what had occurred. He said he would check into it and get back to me.

Stewart Tomlinson also of Southwestern returned my call at 9:22 on 6/18/91, however I was not in the office to accept the call.

I spoke with Mr. Tomlinson on Wednesday, 6/19/91. He stated that the kiln dust had been appropriately watered and palletized, but the haul road had not been watered. He stated that Southwestern was negligent in watering the road. To prevent this situation in the future, he will write a memo to all of the pertinent managers concerning proper palleting of the kiln dust and proper wetting of the haul roads.

He will send the BCHD a copy of the memo.

COUNTY _____

CO # _____ PLT # _____

Date Recd. JUL 16 1991

GENL _____ BY F A X

C O V E R L E T T E R

Brian Andreja
DON'T WASTE COLORADO
P.O. Box 4759
Boulder, CO 80306

DATE: 06/16/91
TIME: 15:12

TEL 303-530-1196
FAX 303-530-1196

0 Pages Follow

TO: Tom Douville

COMPANY: Bldr Cnty Health Dept

FROM: Brian Andreja

COMPANY: DON'T WASTE COLORADO

C O M M E N T S

On sunday, June 16, 1991 between 1:00 and 3:00 PM trucks were observed dumping kiln dust in the quarry on the north side of Hygiene Road at Southwestern Portland Cement. No water trucks were seen and the fugitive emissions from the trucks and quarry were enough to obliterated the skyline up to a half mile downwind of the quarry. Kiln dust contains significant amounts of heavy metals that could accumulate in the soils of farms and dairies downwind, not to mention contamination of the Bldr Creek feeder canal from seepage at the quarry. This is a complaint,

AIR POLLUTION CONTROL - FIELD INSPECTION SHEET

COUNTY NUMBER	SOURCE NUMBER	EMISSION POINTS	DATE
<u>0220</u>	<u>003</u>	<u>001</u>	<u>09/03/91</u>
COMPANY: <u>Southwestern Portland Cement Co.</u>		INSPECTOR: <u>D. Niemiec</u>	
SITE LOCATION: <u>2 miles SE of Lyons</u> <u>Lyons, CO</u>		COUNTY: <u>Boulder</u>	
CONTACT PERSON: <u>Stewart Tomlinson</u>		TIME: <u>9:00 am</u>	
TELEPHONE NUMBER: <u>534-4206</u>		EIS UPDATE: <u>NO</u>	
INSPECTION TYPE: <u>Upset Condition Report</u>		PERMIT NUMBER: <u>NA</u>	
HOURS REQUIRED: <u>0.50</u>			
Prep/Travel: <u>0.00</u>			
Inspection: <u>0.00</u>		COMPLIANCE STATUS: <u>Upset Condition</u>	
Report/EIS: <u>0.50</u>			

Emission Points Subject to NSPS?: NA

At 9:00 am on Tuesday, September 3, 1991, Stewart Tomlinson of Southwestern Portland Cement Company called to report an upset condition which occurred at the plant on Saturday, August 31, 1991. The upset condition resulted in a visible emission from the top of the preheater tower. A six inch steel line which pumps crushed rock developed a small pin hole, about the size of a pencil according to Mr. Tomlinson. This hole created a line of dust to be emitted into the air for approximately 10 minutes. Mr. Tomlinson estimated that 5 pounds of dust was emitted during the episode.

The maintenance crew shut down the line and built a patch to repair the problem.

AIR POLLUTION CONTROL - FIELD INSPECTION SHEET

COUNTY NUMBER	SOURCE NUMBER	EMISSION POINTS	DATE
<u>0220</u>	<u>003</u>	<u>000</u>	<u>01/09/92</u>
COMPANY: <u>Southwestern Portland Cement Co</u>		INSPECTOR: <u>D. Niemiec</u>	
SITE LOCATION: <u>2 miles SE of Lyons</u>		COUNTY: <u>Boulder</u>	
<u>Lyons, CO</u>			
CONTACT PERSON: <u>Bob Trujillo</u>		TIME: <u>1:43 pm</u>	
TELEPHONE NUMBER: <u>823-6685</u>		EIS UPDATE: <u>NO</u>	
INSPECTION TYPE: <u>Notification</u>		PERMIT NUMBER: <u>12B0444</u>	
HOURS REQUIRED: <u>0.50</u>			
Prep/Travel: <u>0.00</u>			
Inspection: <u>0.00</u>		COMPLIANCE STATUS: <u>Yes</u>	
Report/EIS: <u>0.50</u>			

Emission Points Subject to NSPS?: Yes

Bob Trujillo of Southwestern Portland Cement Company phoned to notify us that ice had formed and clogged a port on the opacity monitor. The meter monitors opacity for the kiln. The ice caused the monitor to read in error from 10:00 pm on 1/7/92 to 9:30 am on 1/8/92. The readings recorded during this time period were around 23 - 24%. There was no actual plume opacity only equipment failure. The ice was removed and the monitor appears to be operating appropriately according to Mr. Trujillo.

COUNTY _____

CO # _____ PLT # _____

Date Recd. FEB 13 1992

GENL _____ BY _____

AIR POLLUTION CONTROL - FIELD INSPECTION SHEET

COUNTY NUMBER	SOURCE NUMBER	EMISSION POINTS	DATE
0220	003	009	01/21/92
COMPANY: <u>Southwestern Portland Cement Co</u>		INSPECTOR: <u>D. Niemiec</u>	
SITE LOCATION: <u>2 miles SE of Lyons</u>		COUNTY: <u>Boulder</u>	
<u>Lyons, CO</u>			
CONTACT PERSON: <u>Bob Trujillo</u>		TIME: <u>8:55 am</u>	
TELEPHONE NUMBER: <u>534-4206</u>		EIS UPDATE: <u>NO</u>	
INSPECTION TYPE: <u>Upset Condition Report</u>		PERMIT NUMBER: <u>12B0444-2</u>	
HOURS REQUIRED: <u>0.75</u>			
Prep/Travel: <u>0.00</u>			
Inspection: <u>0.00</u>		COMPLIANCE STATUS: <u>Unknown</u>	
Report/EIS: <u>0.75</u>			

Emission Points Subject to NSPS?: _____

Bob Trujillo of Southwestern Portland Cement Company called at 8:55 am on Tuesday, 1/21/92 to report that the cooler stack opacity monitor had not been operational. According to Mr. Trujillo at 5:10 am on Thursday, 1/16/92 they had a power outage, when the power was returned at 7:30 am the surge apparently burned out a microprocessor in the monitor. The part was reinstalled on 7:30 am on 1/21/92.

The opacity monitor appears to be operating appropriately.

COUNTY _____

CO # _____ PLT # _____

Date Recd. FEB 15 1992

GENL _____ BY _____
