



COLORADO DIVISION OF MINERALS AND GEOLOGY
MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567



The Division of Minerals and Geology has conducted an inspection of themining operation noted below. This report documents observations concerning compliance of the mining operation with the permit and the regulations of the Mined Land Reclamation Board. The report notes 1) Areas of successful compliance; 2) Problems and suggested corrective actions and/or 3) Possible violations to be considered for possible enforcement action by the Mined Land Reclamation Board. OPERATORS SHOULD READ THIS REPORT CAREFULLY BECAUSE IT MAY REQUIRE CORRECTIVE ACTION AND/OR RESPONSES TO THE DIVISION IN ORDER TO AVOID CONSIDERATION OF POSSIBLE ENFORCEMENT ACTION BY THE MINED LAND RECLAMATION BOARD.

MINE NAME: Larimer Quarry OPERATOR: Southdown Portland Cement
COUNTY: Larimer MINERAL: gravel TYPE OF OPERATION: open 112
INSPECTOR(S): Christina L. Kamnikar *CL Kamnikar*
MINE ID # OR PROSPECTING ID #: M-77-341
INSPECTION DATE 06-19-97 DATE OF COMPLAINT NA
INSPECTOR'S INITIALS CLK TIME OF DAY (MILITARY) 9:50 AM
INSPECTION TYPE CODE(1) SI POST INSP. CONTACTS(2) NO
JOINT INSP. AGENCY CODE(2) NO REASON FOR INSP. CODE(3) IE
WEATHER CODE(4) CR OP. REP. PRESENT John Lohr, Southdown Portland Cement

1. INSPECTION TYPE CODE - [CL-IN: IL=Illegal Operation, MI=Monitoring, MP=Mineral Prospect, SI=Surety-related, PR=Pre-operation]
2. POST INSPECTION CONTACTS AND JOINT INSPECTION AGENCY CODE - [CL-AG: NO=None, BL=BLM, CH=Colo. Dept. Health; CL=Land Board, CT=Citizen; CW=Wildlife, FS=Forest Service, HW=Hwy. Dept., LG=Local Government, SE=State Engr.]
3. REASON FOR INSPECTION CODE - [CL-RS: AG=Other Agency Request, CT=Citizen Complaint, IE=Normal I&E Program, HP=High Priority, PY=Priority]
4. WEATHER CODE - [CL-WE: CL=Cloudy, CR=Clear, IN=Inclement - prevented inspection, RN=Raining, SN=Snowing, WD=Windy]

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. IF PB OR PV IS INDICATED, YOU SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF YOUR PERMIT AND APPLICABLE RULES AND REGULATIONS. If PV is indicated, you will be notified under separate cover when the Mined Land reclamation Board will consider possible enforcement action.

GENERAL INSPECTION TOPICS

(AR) RECORDS	Y	(FN) FINANCIAL WARRANTY.	Y	(RD) ROADS.	Y
(HB) HYDROLOGIC BALANCE.	Y	(BG) BACKFILL & GRADING.	Y	(EX) EXPLOSIVES	NA
(PW) PROCESSING WASTE/TAILINGS.	Y	(SF) PROCESSING FACILITIES	NA	(TS) TOPSOIL	Y
(MP) GENL MINE PLAN COMPLIANCE	Y	(FW) FISH & WILDLIFE.	Y	(RV) REVEGETATION	Y
(SM) SIGNS AND MARKERS	Y	(SP) STORM WATER MGT PLAN	Y	(SB) COMPLETE INSP	Y
(ES) OVERBURDEN/DEV. WASTE	Y	(SC) EROSION/SEDIMENTATION.	Y	(RS) RECL PLAN/COMP.	Y
(AT) ACID OR TOXIC MATERIALS.	NA	(OD) OFF-SITE DAMAGE	Y	(ST) STIPULATIONS	NA

Y = Inspected and Found in Compliance PV = Inspected and Possible Violations Noted PB = Inspected and Problems Noted
N = Not Inspected NA = Not Applicable

WHITE - PUBLIC FILE

YELLOW - OPERATOR

PINK - CORRESPONDENCE FILE

OBSERVATIONS

The following observations were made during a follow-up inspection made at the request of the Operator of this 165 acre 112 site.

Since the last inspection of this site on May 1, 1997, all of the grading on the site has been completed, and the topsoil has been placed on all areas which had been excavated. Seeding has also begun on the west 12 acres of the site.

A re-calculation of the bond, based on this completed reclamation work, will be done within the following two weeks.

I & E Contact Address

NAME John Lohr
OPERATOR Southdown Portland Cement
STREET P.O. Box 529
CITY/STATE/ZIP Lyons, CO 80504

cc: Carl B. Mount, DMG

CE
BL
FS
HW
HMWMD (CH)
SE
WQCD (CH)
OTHER

The following problems (PB) and/or possible violations (PV) (and suggested corrective actions) were identified during this inspection. The problems should be corrected by the dates given, or they will become possible violations. The possible violations should be corrected by the dates given to reduce their severity when considered by the Mined Land Reclamation Board. The inspector noted on the previous page should be notified of all corrective actions taken.

No new problems noted at this time.