Alarm Help - MV SERIES -



ALARM ADDRESS	A4.7	ALARM NO.	1123
ALARM TEXT	ATLM CIRCUIT CHECK ERROR.		
Related Signal	Input: X4.7 (MV154/154APC/MV204/184C) •		
CAUSE	Perform M47 Function , PMC detect X4.7 signal = 0 •		
ACTION	1.Check A.T.L.M. System Wiring •		