Alarm Help - MV SERIES -



ALARM ADDRESS	A27.1	ALARM NO.	1301
OP. MESSAGE	NO CONFIRM OF PLT DOWN.		
Related Signal	Input: X16.1 (154APC) • Output: Y8.0 (154APC) •		
CAUSE	Plate change process have problem .		
ACTION	MDI mode ,command M50 for pallet down, then check: 1.Y8.0 activated, pallet not down: check hydraulic pressure, solenoid valve and Y8.0 Relay. 2.Y8.0 activated, pallet down :check signal X16.1 and sensor status.		