Alarm Help - MV SERIES -



ALARM ADDRESS	A23.1	ALARM NO.	2081
OP. MESSAGE	MAG. ZERO POINT RETURN REQUESTED.		
Related Signal			
CAUSE	Each time, when machine power on , this prompt will show on the screen •		
ACTION	1. Select Zero return mode. 2. Select MAG zero return function 3. Press zero return start button		