Alarm Help - MV SERIES -



ALARM ADDRESS	A18.2	ALARM NO.	2042
ALARM TEXT	PAPER FILTER MOTOR OL.		
Related Signal	Input: X4.2 (MV154/154APC/MV204) •		
CAUSE	Breaker trip		
	1.check 3 phase voltage, and voltage phase to phase.		
ACTION	2.wiring loose.		
	3.check output relay.		