Alarm Help - MV SERIES -



ALARM ADDRESS	A15.2	ALARM NO.	2018
OP. MESSAGE	PROGRAM RUNNING, MODE SELECT INHIBIT.		
Related Signal			
CAUSE	During program running and operator desired to change mode , this message occurred •		
ACTION	Stop the program before mode change •		