## Alarm Help - MV SERIES -



ALARM ADDRESS	A25.0	ALARM NO.	1200
OP. MESSAGE	NO CONFIRM OF SPDL GEAR 1.		
Related Signal			
CAUSE	Gear change not success .		
ACTION	Check gear 1 sensor .		