Alarm Help - MV SERIES -



ALARM ADDRESS	A1.1	ALARM NO.	1009
ALARM TEXT	O.T. RELEASE RLY WD. ERROR.		
Related Signal	Input: X6.3 (MV154/154APC/MV204) -		
CAUSE	1 31K4 31K5		OFF but PMC detect signal equal N but PMC detect signal equal 0.
ACTION	Replace relay with new one (DC24V) •		