Alarm Help - MV SERIES -



ALARM ADDRESS	A6.7	ALARM NO.	1139
ALARM TEXT	NO T CMD. & PERFORM M6		
Related Signal			
CAUSE	Wrong Tool call command •		
	Perform Txx M6;		
	M6;		
ACTION	Modify program •		