Alarm Help - MV SERIES -



ALARM ADDRESS	A15.0	ALARM NO.	2016
OP. MESSAGE	THIS MACHINE WITHOUT MAG.		
	ALL OF ATC FUNCTION INHIBIT.		
	PROMPT:MAG. POCKET NO. => D20.		
Related Signal			
CAUSE	The machine without magazine (D20=0), operator desired to perform ATC		
	function, this alarm occurred •		
ACTION	Modify program •		