Alarm Help - MV SERIES -



ALARM ADDRESS	A1.2		ALARM NO.	1010
ALARM TEXT	MACHINE START-UP RLY WD. ERR.			
Related Signal	Input: X6.4 (MV154/154APC/MV204) -			
CAUSE	1:Machine startup Relay OFF but PMC detect signal equal 1 ° 2:Machine startup Relay ON but PMC detect signal equal 0 ° Machine StartUp Relay • Machine StartUp Relay •			
ACTION	Replace relay with new one (DC24V) •			