## Alarm Help - MV SERIES -



ALARM ADDRESS	A24.1	ALARM NO.	2089
OP. MESSAGE	AIR PRESSURE TOO LOW		
Related Signal	Input: X1.7 (MV154/154APC/MV204) , X7.3 (184C) 。		
CAUSE	Pneumatic supplied is lower than 5 kg/cm2 •  Air pressure detector •		
ACTION	Check air supply •		