Alarm Help - MV SERIES -



ALARM ADDRESS	A7.4	ALARM NO.	1144
ALARM TEXT	Z-BRK CTRL. RLY WD. ERROR.		
Related Signal	Input: X6.5 (MV154/154APC/	MV204)	
CAUSE	31K3 Z-AXIS BRAKE FROM BRAKE 31K3 Z-TODIA Z-	equal 1 •	elay OFF but PMC detect signal
ACTION	Replace relay with new one	(DC24V) ·	