## Alarm Help - MV SERIES -



ALARM ADDRESS	A3.1	ALARM NO.	1109
ALARM TEXT	NO CONFIRM. OF POT DOWN.		
Related Sianal	Input: X0.1(MV154/154APC/MV204) , X6.1(184C) 。		
	Output: Y3.1(MV154/154APC/MV204) , Y6.4(184C) •		
CAUSE	When PMC turn on pot down coil & over 5 seconds , the pot down limit switch not		
	detected •		
	1.Check Air pressure •		
	2.Check pot down coil ∘		
	3.Check pot down limit switch •		