Alarm Help - MV SERIES -



ALARM ADDRESS	A33.1	ALARM NO.	1409
OP. MESSAGE	NO CONFIRM OF APC LOAD DOOR CLOSE.		
Related Signal			
CAUSE	APC load door not close while performs M135 .		
ACTION	Check APC load door close sensor .		