Alarm Help - MV SERIES -



ALARM ADDRESS	A33.0	ALARM NO.	1408
OP. MESSAGE	NO CONFIRM OF APC LOAD DOOR OPEN.		
Related Signal			
CAUSE	APC load door not open while performs M134 .		
ACTION	Check APC load door open sensor .		