Alarm Help - MV SERIES -



ALARM ADDRESS	A1.6	ALARM NO.	1014
ALARM TEXT	NO CONFIRM. OF SPDL HEAD COVER		
Related Signal	Input: X2.3 (MV154/154APC/MV204) , X11.2(184C) •		
CAUSE	Signal = 0 , Covers on spindle was		
ACTION	Tight covers up & Reset alarm •		