Alarm Help - MV SERIES -



ALARM ADDRESS	A22.5	ALARM NO.	2077
ALARM TEXT	SPINDLE MOTOR FAN OVERLOAD.		
Related Signal	Input: X7.7 (MV154/154APC/MV204) , X10.0 (184C) •		
CAUSE	Spindle Motor Fan breaker is ove	rload •	11Q1 BREAKER (SPINDLE MOTOR FAN) STOP STOP START PARTICULAR START STA
ACTION	Turn on the breaker at cabinet as Cancel alarm by reset button	1	l indicated. • n FANUC panel •