Alarm Help - MV SERIES -



ALARM ADDRESS	A25.1	ALARM NO.	1201
OP. MESSAGE	NO CONFIRM OF SPDL GEAR 2.		
Related Signal			
CAUSE	Gear change not success .		
ACTION	Check gear 2 sensor .		