Alarm Help - MV SERIES -



ALARM ADDRESS	A3.0	ALARM NO.	1108
ALARM TEXT	NO CONFIRM. OF POT UP.		
Related Signal	Input: X0.0 (MV154/154APC/MV204) , X6.0(184C) -		
	Output: Y3.0 (MV154/154APC/MV204) , Y6.3(184C) -		
CAUSE	When PMC turn on pot up coil & over 5 seconds, the pot up limit switch not		
	detected •		
	1.Check Air pressure •		
	2.Check pot up coil ∘		
	3.Check pot up limit switch •		
ACTION			