Alarm Help - MV SERIES -



ALARM ADDRESS	A1.0	ALARM NO.	1008
ALARM TEXT	EMG. EXPAND MODULE WD. ERR.		
Related Signal	Input: X6.2 (MV154/154APC/MV204) •		
CAUSE	2:Mac CONTROL POWER OF EMG STOP CONTROL POWER OF NC CONTROL POWER OF		out PMC detect signal equal 1 • PMC detect signal equal 0 •
ACTION	Replace relay with new one (DC	24V) •	