Alarm Help - MV SERIES -



ALARM ADDRESS	A24.0	ALARM NO.	2088
OP. MESSAGE	LUBRICATION LEVEL TOO LOW		
Related Signal	Input: X1.6 (MV154/154APC/MV204) , X7.2 (184C) 。		
CAUSE	LUBRICATION LEVEL TOO LOW •		
ACTION	Fill oil into lubricant , as marked	level。	