Alarm Help - MV SERIES -



ALARM ADDRESS	A4.5	ALARM NO.	1121
ALARM TEXT	MAG. NOT INPOSITION.		
Related Signal	Input: X1.2 (MV154/154APC/MV204) , X7.0 (184C) 。		
CAUSE	Perform pot down action, but MAG. Inposition sensor not detected •		
ACTION	 Check detector distance from proximity to "DOG", (must within 1mm). Check wiring is loss? If Hardware OK, Please rotate MAG. By manual Mode, the MAG. will automatic search inposition signal and stop. 		